

Technical Service Information

ACURA 4 SPEED HYDRAULIC NO UPSHIFT

COMPLAINT: No upshifts (T.V. and governor pressure ok).

CAUSE: Mis-assembly of the CPV valve and spring.

CORRECTION: Remove and install correctly.




Figure 1

Copyright © 2000 ATSG