

MAINTENANCE MANUAL — MOCK / TRAINING

B737 — Maintenance Manual

FlySmart reference document · Revision B/C

ATA 36 Pneumatic

36-11 Bleed air leak detection

Overheat detection loops along the bleed ducts trigger a DUCT OVERHEAT/LEAK indication; the affected bleed is isolated automatically and annunciated on the air systems panel. Inspect the loop routing if false indications occur.

ATA 78 Engine — Thrust Reverser (FADEC)

78-31 Reverser inhibit logic

Reverser deployment is inhibited unless the related conditions (on-ground logic, throttle at idle) are satisfied, per the FADEC interlocks. A failed interlock latches a fault and prevents deployment.

Warning: never defeat a reverser interlock for troubleshooting on a live system.

B737 — Maintenance Manual (MOCK). For training/demonstration only.