



## 5.9.2 Case 23



## 5.9.2.1 Contents

Item Name/Description	Qty
Field Border Frame	2
Ramp Sheetmetal	1
5ft Truss	2
4ft Truss	2
4-way Corners	1
Floor Support	4
Cage Weldment - Blue	3
Processor Weldment	1
Truss Base Long	1
Lower Front Plastic	2
Upper Front Plastic	2
Ramp	2
Bumper Plastic	2
Back Divider Plastic	2
Game Piece Holder Side	4
Game Piece Holder Top/Bot	4
Game Piece Holder Back	2



firstinspires.org/robotics/frc

Frame Support Leg	4
Backboard	2
	_
Side Panel w/Vinyl	2
Top Panel	2
Humanside Panel	2
Rib, Blue	3
Rib, Red	3
Holder, April Tag	4
Left Side Assembly	2
Right Side Assembly	2
Truss Base Normal	1
Brace, Barge End	2
Extra Wall Panel Briweld	2
Pin Connector - Briweld	2
Pin Connector - AM	2
Net Tube, Outer	4
Net Tube (Assembly)	4
2x6 Gridwall	2
Carabiners	14





## 5.9.2.3 Packing Steps

1.




















PRESENTED BY -11145



Pack the Coral Station floor supports and the blue cages to the case in the shown orientation. **ÓS SOLID**WORKS Modeling Solutions Partner















PRESENTED BY -1/14-5


9.








































18.





Modeling Solutions Partner








PRESENTED BY -1/14-5











Pack the Processor Weldment Pin
Connectors into the space inside
the Processor Weldment. If you are
packing a field with a Briweld Field
Perimeter, also pack the Extra
Processor Plastic

2x











Pack the 2'x6' fence structures in the case as shown. Cable tie to the Processor Weldment for stability.

Finally, tuck the carabiners into the end of the case inside the Truss.

14x

Solidorers

Modeling Solutions Partner

24.

**Modeling Solutions Partner**