

EXHIBIT BUNDLE

SCAFFOLD INSPECTION AND HANDOVER RECORD — TWO VERSIONS

Work at Height Regulations 2005, reg. 12 and Schedule 7

Exhibit references	GP/1 (Version A) and GP/2 (Version B)
Record reference (both)	TL/BW/INSP/113
Provenance of Version A	Produced by Meridian Structures Limited on 24 November 2023 in response to HSE notice under s.20(2)(j) HSWA 1974. Supplied as a 300 dpi monochrome scan of a paper document. The paper original has not been produced. Meridian states the original was 'retained by TowerLine'.
Provenance of Version B	Recovered on 8 February 2024 from a Samsung Galaxy Tab A8 (IMEI 35-993042-118776-2) held by the liquidator of TowerLine Access Ltd. Extraction by Northmoor Digital Forensics Ltd, case NDF-24-0331, using Cellebrite UFED 4PC 7.62. Hash of extracted database recorded and verified.
Status	Authenticity of Version A is disputed. Mr Pyle asserts (D05) that he did not complete Version A. Meridian does not accept Version B is the operative record.

PART 1 — VERSION A (exhibit GP/1)

Reproduced from the scanned paper document supplied by Meridian Structures Limited.

Field	Entry
Record no.	TL/BW/INSP/113
Site	Brackenmoor Wharf, Hunslet, Leeds
Structure inspected	East elevation independent tied scaffold, levels 1-8 incl. loading bays LB-6, LB-7
Type of inspection	7-day statutory / post-alteration
Date and time	13 November 2023, 15:30 - 16:30
Inspector	G. H. Pyle, CISRS Advanced 41-77104
Ties	SATISFACTORY
Bracing	SATISFACTORY
Boards / guardrails / toeboards	SATISFACTORY
Foundations / base plates	SATISFACTORY
Loading bay LB-6	SATISFACTORY
Loading bay LB-7	SATISFACTORY
Defect identified?	NO
Safe working load displayed	YES
Comments	None.
Handed over to (principal contractor)	R. Delacroix-Hale, Meridian Structures Ltd
Signature of inspector	[manuscript signature reading 'G Pyle']
Signature of recipient	[manuscript signature, illegible]
Date of handover	13 November 2023

Forensic note on Version A (Northmoor Digital Forensics Ltd, report NDF-24-0331, section 6): The scanned image shows compression artefacts consistent with a single generation scan of a printed page. The manuscript signature in the inspector field is, in the opinion of Ms C. Anandarajah-Beck (document examiner, instructed by the CPS), 'not a natural signature but is consistent with a reproduction, most likely by photocopying or digital lift, of the signature appearing on TowerLine document TL/BW/INSP/106 dated 06.11.2023'. Ms Anandarajah-Beck grades this conclusion as 'probable' on the ENFSI nine-point scale, not 'conclusive', and notes she has not examined an original.

PART 2 — VERSION B (exhibit GP/2)

Reproduced from the extracted application database. Field names are as they appear in the TowerLine inspection application schema.

Database field	Value
record_ref	TL/BW/INSP/113
site_id	BW-LEEDS-2023
structure	East elev. independent tied, L1-L8 incl. LB-6, LB-7
inspection_type	7_DAY_STATUTORY
inspection_start	2023-11-13T15:28:41Z
inspection_end	2023-11-13T16:34:07Z
inspector_user_id	TL-0119 (G.PYLE)
ties_status	DEFECT
bracing_status	SATISFACTORY
boards_guardrails_status	SATISFACTORY
foundations_status	SATISFACTORY
lb06_status	SATISFACTORY
lb07_status	DEFECT_DO_NOT_USE
defect_flag	TRUE
swl_signage_present	TRUE
comments	3 NO TIES MISSING L6/L7 EAST ELEV - DO NOT LOAD BAY LB-7 UNTIL RECTIFIED
handover_to	(null)
inspector_signature_captured	FALSE
record_committed	2023-11-13T16:52:19Z
record_status	COMMITTED / NOT_SYNCED
last_sync_attempt	2023-11-13T16:53:02Z - FAILED (no network)
subsequent_sync	(none)
edit_history	1 edit: 2023-11-13T16:44:55Z field comments changed from " to current value; no edits after commit

Forensic note on Version B: the record was committed locally at 16:52:19 on 13 November 2023 and was never synchronised to TowerLine's server. It follows that no person other than the holder of the device could have read it from the server. The device was locked with a four-digit PIN. The device was recovered from a storage crate at TowerLine's Wetherby depot, not from Mr Pyle. There is no record of who placed it there. The system clock was verified against the network time record and was accurate to within 4 seconds.

PART 3 — MATTERS ARISING (prepared by the CPS reviewing lawyer, for information only)

- If Version B is the true record, no valid handover took place and LB-7 was loaded without a statutory handover.
- If Version A is the true record, Mr Pyle's second statement (D05) is false and his first statement (D04) is true.
- Neither version bears a Meridian receipt stamp. Meridian's own procedure MSL-TW-03 requires the handover to be logged in the temporary works register on receipt. No such log entry exists for record 113.
- The paper original of Version A has never been produced. Meridian says TowerLine held it. TowerLine's liquidator says the paper records were destroyed by a contractor, Skelbrook Confidential Waste Ltd, on 19 January 2024, which is after service of the s.20 notice on Meridian but before the liquidation.
- It is not presently possible to say that the two versions are inconsistent as a matter of logic: it is arguable that a defect was recorded at 16:52 on the tablet and that a satisfactory handover was later signed on paper the same evening after remedial work. There is, however, no record of any remedial work, no materials requisition, and no operative has been identified as having carried it out.