



Service Bulletin Log

Work Order No. W107736

Component Part No.: 2801A0000-03

Component Description: MLG Shock Strut

Year Introduced	A/C MFG Service Bulletin No.	OEM Service Bulletin No.	A.W.D. No.	IDENTIFICATION METHOD	Description	Not Carried out.	Previously Carried Out.	AT Carried Out	Optional	Recommended	Mandatory
12/Apr/2006	170-32-0011	170-2801A-32-01	N/A	2801A/2802A0000-02 to -03.	Replacement of MSE Seal	STAMP	STAMP	STAMP		X	
23/Apr/2015	170-32-0021 R2	170-2244A-32-01 R1	N/A	2244A0000-03/-04 to -05	Shimmy Damper replacement	STAMP	STAMP	STAMP			X
23/Apr/2015	170-32-0021 R2	2801A32-07	N/A	2801A/2802A0000-02/03 to -04.	MLG Shock Strut PN 2801A0000-03 and PN 2802A0000-03 - Reidentification of Shock Strut into PN 2801A0000-04 and 2802A0000-04	STAMP	STAMP	STAMP			X
27/Oct/2009	170-32-0042	2801A-32-02	N/A	Log	Downlock release Actuator attachment flange assembly bush replacement	STAMP	STAMP	STAMP		X	
28/Oct/2019	170-32-0060 R1	2801A-32-09 R2	N/A	2801A/2802A0000-05 to -06.	UPR Bearing Support improvement Make sure this SB and 2801A-32-06 incorporated	STAMP	STAMP	STAMP			X
15/Jan/2019	170-32-0049 R2	2801A-32-05	N/A	2801A/2802A0000-04 to -05 Log	Improvement of the Side Stay attachment Bolt	STAMP	STAMP	STAMP		X	
30/Sep/2010	170-32-0046	32-11-170-MLG-02	N/A	Log	Replacement of the Uplock Roller	STAMP	STAMP	STAMP			X
11/Jan/2013	170-32-0047 R1	32-11-170-MLG-01 R1	N/A	Amdt. A	Replacement of the Bolt P/N 1840-0029	STAMP	STAMP	STAMP		X	
27/Jan/2012	170-32-0052 R1	2801A-32-04	N/A	Log	Servicing Chart replacement	STAMP	STAMP	STAMP			X