



870 Maude Avenue
Sunnyvale, California 94085
Tel (408) 774-9060
Fax (408) 774-2169
E-mail: www.plxtech.com/contacts
Internet: www.plxtech.com/netchip

NET 2272 USB 2.0 Interface Controller

Errata

For Rev 1A Device

This document contains material that is confidential to PLX Technology. Reproduction without the express written consent of PLX is prohibited. All reasonable attempts were made to ensure the contents of this document are accurate, however no liability, expressed or implied is guaranteed. PLX reserves the right to modify this document, without notification, at any time.

NOTE: These errata apply to the NET2272 Controller Revision 1A.

Each erratum contains one or more groups consisting of a “Post Date” and text. Errata are updated with additional text as more information becomes available. When two sections of the same erratum are inconsistent, the one with the most recent date applies.

Revision History

Revision	Issue Date	Comments
1.0	February 3, 2005	Revision 1A initial erratum
1.1	August 23, 2006	Added erratum 630-0213-0103
1.2	December 1, 2006	Removed erratum 630-0213-0102

