

Tourer Habitation
Service Record

Habsheet
195-197 Wood Street
E17 3NU
London, Uk
07506 078673
Habsheet.com

CUSTOMER
Andy Carry (Sample)

MAKE AND MODEL
Bailey Phoenix

CRIS / VIN
56ES343 200053

Chassis and running gear	P	F	N/A	R	Comments
Coupling head	P				
Stabiliser	P				
Coupling gaiter	P				
Breakaway cable and clip		F			Failed on inspection. Attention needed.
Drawbar	P				
Corner steadies	P				
Spare wheel carrier	P				
Jockey wheel	P				
Chassis				R	Rectified at this service
Brakes	P				
Wheels and tyres	P				
Axle and suspension	P				
Handbrake	P				

Electrical	P	F	N/A	R	Comments
13-pin and 7-pin plugs, cables and stowage	P				
Road lights and reflectors	P				
Leisure battery	P				
Battery compartment	P				
Fridge on 230V and 12V	P				
Interior lighting and equipment	P				
Awning light	P				
ELV wiring – visual inspection	P				
Mains inlet and hook-up lead	P				
Earth bond continuity	P				
Consumer unit – RCD load test	P				
230V sockets	P				
Charge voltage	P				
230V appliances, fans and lighting – operation	P				
Aftermarket equipment	P				

Gas	P	F	N/A	R	Comments
Regulator, hose, pipework and manifold	P				
Tightness test	P				
Gas appliances – operation and flame failure devices	P				
Cylinder security	P				
Dispersal vents clear	P				

Water	P	F	N/A	R	Comments
Pump, pressure switch and microswitches	P				
Taps, valves, pipes and tank	P				
Water inlets	P				
Waste system	P				
Toilet	P				

Bodywork	P	F	N/A	R	Comments
Doors and windows	P				

Tourer Habitation
Service Record

Habsheet
195-197 Wood Street
E17 3NU
London, Uk
07506 078673
Habsheet.com

CUSTOMER

Andy Carry (Sample)

MAKE AND MODEL

Bailey Phoenix

CRIS / VIN

56ES343 200053

Bodywork – continued

	P	F	N/A	R	Comments
Bodywork and roof – general condition	P				
External seals and bonded joints	P				
Roof straps	P				
Grab handles	P				
Number plate – BS AU 145d marking, security, legibility			N/A		
Floor	P				
Furniture	P				
Blinds and fly screens	P				
Rising roof	P				
Damp test – recorded on the damp report	P				

Ventilation

	P	F	N/A	R	Comments
Fixed ventilation, low and high	P				
Roof lights	P				

Fire and safety

	P	F	N/A	R	Comments
Smoke alarm – test button, circuit, sounder	P				
CO alarm – test button, circuit, sounder	P				
Fire extinguisher – housing security	P				

Smoke alarm expiry

06/2033

CO alarm expiry

03/2033

Fire extinguisher expiry

N/A

Service information, additional work and observations

Repaired

230v Hook Up current Draws: - Charger 0.4amp, Fridge 0.6 amps	
Aldo Boiler 4.7/8.7/13.3 Amps, Hob 0.3/0.4/0.8/1.6/2.7/3.5 amps	
Check video sent on WhatsApp.	

EICR offered

Yes / No / N/A

Wheel bolt torque checked

Torque setting (Nm)

130

Tyres	N/S front	N/S rear	O/S front	O/S rear	Spare
Tyre age*	14/17	14/17	14/17	14/17	18/19
Tyre pressure PSI or BAR	58	58	58	58	58
Tyre tread depth (mm)	7.4	7.4	7.4	7.4	7.4

Replace beyond five years; never use beyond seven.

- ☒ Gas turned off
- ☒ Lights off
- ☒ Roof lights latched
- ☒ Water pump off
- ☒ Windows locked
- ☒ 12V master off
- ☒ Cupboards closed and latched
- ☒ Old parts left with the vehicle
- ☒ Exterior lockers locked
- ☒ Protective coverings removed
- ☒ Exterior door locked
- ☒ Service book stamped

Battery rest voltage (V)

12.9 V

RCD trip time at 1xIΔn (ms)

26/36

Earth bond, chassis (Ω)

0.02

Earth bond, gas (Ω)

0.04

Charger voltage (V)

13.8 V

Gas hose expiry / manufacture date

02/2022

Regulator age

2015

Note Appliances are checked for operation only, not against the manufacturer's performance figures. Further servicing may be needed for warranty purposes.

This record describes the caravan at the time the service was completed. It is not evidence of its condition at any other time.

Service technician	Signature	
Double-checked by	Signature	
Customer signature	Date	20/09/2026

Tourer Damp Report

Andy Carry (Sample)

Bailey Phoenix

56ES343 200053

0 - 15% Normal for a dry structure. Readings in this range are not recorded – only figures above 15% appear on this report.

15 - 20% A trace of moisture. Read against the other figures taken on this vehicle, and have the area checked again after three months.

20 - 30%	Moisture is entering the structure. The area should be investigated to establish how water is getting in, and resealed before the material degrades further.
----------	--

30% and above	High enough that the structure itself may already be damaged. Resealing is likely to be needed, followed by rectification of the damage without delay.
---------------	--

Note These readings describe the vehicle on the day it was tested. Moisture content moves with the weather, and a dry figure today is no guarantee against damp appearing later. No liability is accepted for damp found after this date.

Testing covers the interior of the habitation area only.

Lockers and storage areas are tested as found. Belongings are not removed, so any surface they cover has not been read.





Tourer Damp Report

Habsheet
195-197 Wood Street
E17 3NU
London, Uk
07506 078673
Habsheet.com



CUSTOMER
Andy Carry (Sample)

MAKE AND MODEL
Bailey Phoenix

CRIS / VIN
56ES343 200053



Calibration check figure
14
Weather conditions
Dry
Ambient temperature
18°C
Meter – make and model
Protimeter survey master



Service technician		Signature	
Customer signature		Date	20/09/2026