Confined Space Entry Procedure

1. Permit and atmospheric limits

A confined space entry permit is required before entry.

The acceptable oxygen range is 19.5% to 23.5%.

Test for flammable gas and hydrogen sulfide before entry.

Required PPE includes a full-face respirator, gloves, and a safety harness.

2. Entry and rescue

Isolate and lock out all energy sources before entry.

Ventilate the space and retest the atmosphere before entry.

A standby attendant must remain outside the space during entry.

If a worker collapses, call emergency services and use the tripod rescue system.

3. Communication, evacuation, and records

Maintain continuous communication with the attendant.

Evacuate immediately if the gas monitor alarms.

Keep the entry permit for one year after the work.

Retrain entrants and attendants every year.