**New Journal** 

- 1: Component.405\_Laser\_Power.Position = 50 2: pulsetime = 800

- Total\_Regions = 0
  3: Select Focus Device(Device Name = Leica Z Motor)
  4: Start Continuous Focusing(0)