New Journal

- 1: Component.405_Laser_Power.Position = 100
- 2: pulsetime = 800
- 3: pulsetime2 = 200 4: pulsetime3 = 50
- 5: size_dilate = 0
- Total_Regions = 0
 6: Select Focus Device(Device Name = Leica Z Motor)
- 7: Start Continuous Focusing(0)