New Journal

- 1: Component.405_Laser_Power.Position = 100 2: pulsetime = 800
- 3: size_dilate = 0

Total_Regions = 0

- 4: Select Focus Device(Device Name = Leica Z Motor)
 5: Start Continuous Focusing(0)