

WORK PROCEDURE

PRO-OP-SM-001A

PRE-OPERATION PROCEDURE WITH THE STOPEMASTER

OBJECTIVE

The objective of this procedure is to define safe work methods to prepare the STOPEMASTER before operating

APPLICATION

This procedure applies to all employees of MACHINES ROGER INTERNATIONAL.

INTERPRETATION

The personnel having authority for the interpretation of this document is the Operations Manager. Any request for modification, revision or update must be made to this person.

RESPONSABILITIES

The supervisor is responsible for applying and following this procedure. The driller must follow this procedure and all client's procedures. The Driller is responsible for the day-to-day operation of the drill and other on-site equipment required to support the operation. The driller needs the training for all equipment he operates.

- The Driller is responsible for obtaining the maximum possible quality in any given ground condition, while achieving maximum production and maintaining a safe and efficient work environment;
- The Driller is responsible for the general condition of all site, equipment and tools;
- The Driller is responsible for obtaining optimum life out of drilling tools and consumables;
- The Driller is responsible for the location of the collar of the hole, ensuring correct alignment with front and back sides, offsets, depth and setting the drill at the correct angle;
- The Driller is responsible for training new Drillers in safe work methods, if requested;

PRE-OPERATION PROCEDURE WITH THE STOPEMASTER

- The Driller is responsible for complying with all environmental regulations as legislated by local Government;
- The Driller is responsible to submit a shift report and to fill in the job's log book.

PROCEDURE

INSPECTION

A JOB SITE INSPECTION has to be performed before entering the site.

The driller must do his workplace inspection and fill his workcard, then he must do the inspection of the drill and fill the form at the beginning of the shift. If there's a mechanic problem or a safety issue, he can fix the problem or call his supervisor.

1. Pre-operation checks must be carried out on all equipment before it is used;
2. Broken parts or loose parts should be repaired or replaced as soon as possible;
3. All grease fittings must get grease before starting up;
4. It's allowed to operate when the rubber on the hose is worn out but frayed hoses should be replaced before they begin to burst;
5. Make sure whip checks are in good condition and in place;
6. When checking for hydraulic leaks, never pass your hand over hoses;

LOCATE DRILL STATION IN A SAFE MANNER


1. Level plan, long section and cross-sectional drawings for drill stations must be released by client's supervision or engineering personnel prior to drilling;
2. Determine identification number for stope by reading level plans;
3. Locate drill station and follow procedure before moving any equipment to site;
4. Determine degree of hole and whether or not it is upholes or down holes;
5. Verbally confirm level with drill supervisor or foreman;
6. Confirm approximately how far you will travel before reaching the station;

PRE-OPERATION PROCEDURE WITH THE STOPEMASTER

7. Request information regarding ventilation, e.g.: Does a fan require to be turned on and here are the phones and/or refuge station located?;
8. If you are unfamiliar with the mine, have a Company employee accompany you to your station.

PRE-MOVE INSPECTION OF DRILL LOCATION

1. Check travel way from shaft/ramp to drill location to ensure proper clearance of equipment;
2. After locating drilling area, first check for air quality, e.g.: Is air moving? Is it hot and stuffy? Are there fans or ventilation tubing that need to be turned on?;
3. Visually inspect backs and walls for ground conditions and ground support systems;
4. Perform a good scaling before you bring the equipment in the stope;
5. All unsafe conditions must be reported to Mine and/or MRI supervision;
6. The stope should be cleaned out by scoop or any mucking devices if needed;
7. Are the survey stations clearly marked and reference lines painted or hanging? Are the rings marked on the walls?;
8. Locate air and water headers. Where required, locate electrical supply panel. Check compatibility of quick connects;
9. Inspect for open holes. Follow Company policy for barricading and reporting open holes and open stopes;
10. Is there sufficient back height for equipment? ;
11. USE longer rods for collaring upholes;
12. Fill out job site inspection sheet BEFORE carrier is moved to new drilling area;
13. Make sure you have good communication (phone, radio...).



Christian St-Amour
Operations Manager