


1. If the control signal comes from a 5V supply, R1 should be increased to 180 Ohms.

3. When using a MOC3061M (600V), R2 should be changed to 360 Ohms.



File: Output_stage.kicad_sch

Size: A5

Date: 2023-09-16

Rev: 2.0

Id: 1/1