Unnamed tributary

wa-0625-r-001

Sedimentation Risk Index

44

2.4mi SW of Florala Common:

Crossing Structure: DS

Drainage:
Land owner:

Pond Creek <u>GPS:</u> 30.983133, -86.359481 Thomas Kilpatrick-US, Walton Properties LLP-DS

<u>County</u>: <u>PLSS(T-R-S)</u>: <u>Parcel No.</u>: Road Name:

Walton

6N-21-29/32 5; 4.003 Varnum Rd

Florida State:



Risk Factor	Ranking	Score
US Channel Morph	PONDED	1
DS Channel Morph	С	5
DS Bank Alteration	MINOR/PARTIAL	3
Upstream Skew Angle	<5°	5
Crossing fill condition	Good/Vegetated	5
Inlet/Outlet Condition	No Impairment	5
Road Approach Material	All Sand/Clay	3
Potential Eroded Volume Mean	<21 y ³	5
Approach Slope Mean	2.1-4%	3
Soil K Factor	0.21-0.40	3
Upstream Rt Outlet	Vegetated	1
Upstream Lt Outlet	Vegetated	1
Upstream Rt Ditch	Bare soil	0
Upstream Lt Ditch	Bare soil	0
Downstream Rt Outlet	Vegetated	1
Downstream Lt Outlet	Vegetated	1
Downstream Rt Ditch	Bare soil	0
Downstream Lt Ditch	Bare soil	0
Outlet Total	Improved Outlet System	5
Ditches Total	Unimproved Drainage System	1
SRI Total	Medium Risk	44

Additional Site Features	
Crossing Type and Quantity:	Bridge, 1
Crossing Materials:	Wood
Soil Types:	13,14,15,22,23,60,61
Rt Approach Prism Fill:	0.25in
Lt Approach Prism Fill:	0.25in



Feature	Within Range	Descriptive Field
303(d)	No	N/A
Wetland Species	No	N/A
Rare and Imperiled	Yes	SPECKLED CHUB, IRONCOLOR SHINER
Land Use/ Cover	Yes	VACANT RESIDENTIAL, AGRICULTURAL/ WETLAND FORESTED MIX
Candidate Mussels	No	N/A
Sturgeon C H	No	N/A

Notes: Fencing across DS channel causing sediment buildup