## Gum Creek

## wa-1026-001

Severity Score 10.5

<u>Common:</u> 7.3mi NE of De Funiak Springs, .04mi DS HWY 331 <u>Drainage</u>: Shoal River <u>GPS</u>: 30.801519827, -86.194956251

<u>Land owner</u>: Christopher Marshall

<u>County</u>: <u>PLSS(T-R-S)</u>: <u>Parcel No.</u>:

Walton 4N-20W-36 <u>State</u>:

Florida





Risk Factor	Ranking	Score
Channel Stability	Fair	1
Channel Alteration	In Recovery	1
Bank Erosion	Active	1
BEHI	High	0.5
Local NPSP	Obvious Sources	1.5
Shoring Structures	Present	1.5
Pipe Discharge	Not Present	0
Water Odors	Not Present	0
Fish Passage Barrier	Present	1.5
RB: Riparian Buffer	0-29 ft	0.75
LB: Riparian Buffer	0-29 ft	0.75
RB: Floodplain Access	None	0.75
LB: Floodplain Access	None	0.25
	River Threat Index:	10.5

Feature	Within Range	Descriptive Field
303(d)	No	N/A
Wetland Species	No	N/A
Rare and Imperiled	No	N/A
Land Use/ Cover	Yes	RESIDENTIAL/ STREAMS AND WATERWAYS
Candidate Mussels	No	N/A
Sturgeon C.H.	No	N/A
Stream Char	Site Features anel Woody Mo	<del></del>
Impoundmer Substrate Co	<del></del>	Rip Rap Medium Sand

Sand and Clay

Notes: Rip rap has been used as a shoring structure around the bridge and large quantities have fallen in the stream channel causing a fish passage blockage during low flow stages. A house nearby is also noted as a source of NSPS.

Bank Material: