Deadfall Creek

ok-0512-r-005

Sedimentation Risk Index

Florida

State:

40

7.4mi NW of Crestview Common:

Yellow River <u>Drainage</u>: Land owner: Cheryl Mack *GPS*: 30.862141426, -86.613178012

Okaloosa County: $\overline{PLSS(T-R-S)}$: 4N-24-11

Parcel No.:

Road Name: Old River Rd





Crossing Structure: DS

Risk Factor	Ranking	Score
US Channel Morph	E	5
DS Channel Morph	E	5
DS Bank Alteration	NATURAL	5
Upstream Skew Angle	<5°	5
Crossing fill condition	Fair/Rip Rap	3
Inlet/Outlet Condition	No Impairment	5
Road Approach Material	All Sand/Clay	3
Potential Eroded Volume Mean	>40 y ³	1
Approach Slope Mean	>4%	1
Soil K Factor	< 0.20	5
Upstream Rt Outlet	Bare soil	0
Upstream Lt Outlet	Bare soil	0
Upstream Rt Ditch	Bare soil	0
Upstream Lt Ditch	Bare soil	0
Downstream Rt Outlet	Bare soil	0
Downstream Lt Outlet	Bare soil	0
Downstream Rt Ditch	Bare soil	0
Downstream Lt Ditch	Bare soil	0

Additional	Site	Featu	res
Cuanina T.			4

Outlet Total Ditches Total

SRI Total

Crossing Type and Quantity: Bridge, 1 Crossing Materials: Wood

23,36,37,38,39,41,43,44,52,56 Soil Types:

Unimproved Outlet System Unimproved Drainage System

Medium Risk

Rt Approach Prism Fill: Lt Approach Prism Fill: 1.0in



PART TO THE PART OF	#2####################################	222 - ALEXANDER	150000	SAUPKU OF TEN
			Escar	thia Covington
公 有				THE STATE
				"是是这种的
是行為於		PALS I		STEE STEEN
新名的	AND STATE	34 M		AND THE PARTY OF T
			1 0000	外极定为小的。
医			A SOUTH	Okaloosa Walton
EMILE	200	THE PART OF		2
The second	A PRODUCTION			ENTERNATION OF THE PROPERTY OF
		A STATE OF	"是一个一个	
S. A. C.		And the last	2000年4月	"你不是我们
L'ENERGE	A CONTRACTOR	人名英格兰	The second	
可能源法	经验	No. of the last of		A CONTRACTOR
1199年112		不是是快速		发生了
			医	
				基验性混乱
		en la company		Google
Imagery Date Feb 22 2007		14 30 802224 Int. 36 812835 Inc.		Carrie Manager

Feature	Within Range	Descriptive Field
303(d)	No	N/A
Wetland Species	No	N/A
Rare and Imperiled	No	N/A
Land Use/ Cover	Yes	AGRICULTURAL/ ELECTRICAL POWER TRANSMISSION LINES
Candidate Mussels	No	N/A
Sturgeon C.H.	No	N/A

Notes: DS altered by power line crossing.

40