


O-ring failure in the Challenger

On January 28, 1986, the Space Shuttle Challenger (OV-099) broke apart 73 seconds into its flight



O-ring failure in the Challenger



<https://slideplayer.com/slide/17983085/>