To Fix:
1. Cap spacing
2. D1 pass through — DONE
3. Double U3 component — DONE
4. General review for other issues



TPH-50 Turbopump Controller Rev. 2
Circuit Design: John Futter
PCB Layout: Nicolas Krause