PINNACLE INC - SKVT

WORK DETAILS

TABLE OF CONTENTS

- I. CASSETE PCB REPAIR (PAGE-3)
- 2. MOTORISE VALVE (PAGE-4)
- 3.Y STAINER SERVICE (PAGE-7)
- 4. FCU DEEP CLEANING (PAGE-12)
- 5. CASSETTE AC SERVICE (PAGE-16)
- 6. AHU SERVICE (PAGE-21)
- 7. TEMPERATURE METER (PAGE-25)
- 8. BUTTERFLY VALVE 150 MM (PAGE-28)
- 9. BUTTERFLY VALVE 125 MM (PAGE-30)
- 10. BUTTERFLY VALVE 100 MM (PAGE-32)


- 11. BUTTERFLY VALVE 65 MM (PAGE-35)
- 12. 1/4 BALL VALVE (PAGE-38)
- 13. WATER PRESSURE GUAGE (PAGE-40)
- 14. FALSE CEILING (PAGE-43)
- 15. DESCALLING (PAGE-44)
- 16. IDU MOTOR (PAGE-47)
- 17. SENSOR (PAGE-48)
- 18. BALL VALVE 3/4 INCH (PAGE-49)
- 19. CONDENSER LINE PUMP OR CHILLED WATER LINE PUMP SERVICE (PAGE-53)

CASSETE PCB REPAIR

BEFORE AFTER REPAIR







MOTORISE VALVE

BEFORE- DEFECTIVE

AFTER- NEW INSTALLED





























Y STAINER SERVICE











































FCU DEEP CLEANING































CASSETTE AC SERVICE

BEFORE



AFTER









































AHU SERVICE









































TEMPERATURE METER

DETAILED GRAPH IS SHARED

























BUTTERFLY VALVE 150 MM



















BUTTERFLY VALVE 125 MM

















BUTTERFLY VALVE 100 MM





























BUTTERFLY VALVE 65 MM


























1/4 BALL VALVE

BEFORE AFTER





















WATER PRESSURE GUAGE

BEFORE - FOULTY

AFTER CHANGE

























FALSE CEILING









DESCALLING





























IDU MOTOR

BEFORE



AFTER



SENSOR

BEFORE



AFTER



BALL VALVE 3/4 INCH

BEFORE AFTER



































CONDENSER LINE PUMP OR CHILLED WATER LINE PUMP SERVICE

























THANK YOU.