

USB C 2.0 Connector
Battery Connector
16V Polyfuse with atleast 2A current draw
LDO to 3.3V
9 Axis IMU
Caps must be crystal load caps
Altimeter/Barometer
Radio Clock
Caps must be crystal load caps
Ferrite Bead should be around 600 ohms with 100mhz
All Capacitors under the Radio Trancelver must be RF match caps Inductors must be RF rated and low Q with good tolerances
BUCK TO 4.16V
XTAL1
NX3225GA-25.000M-STD-CRG-2
Caps must be crystal load caps
STM CLOCK
RADIO TRANCEIVER
LED_RED
LED STATUS
CONTROL JST CONNECTOR
DEBUG/FLASH PINS
STM32
ADXL375 ACCELEROMETER

Gene Kang