1B 1A 2A 2B 1B 1A 2A 2B STEPPER DRIVE

EN STEP DIR

PC13|PC0 |P82 | X

PB12|PC2 |P89 | Y TMC UART PIN

| TX = RX | PC7 | X | Y | PD2 | Y | PC12 | Z | E | E | PC11 | E | PC12 | E | PC11 | E | PC12 | E | PC12 | E | PC13 | E | PC14 | PC15 | PC3 PC1 RST PB11 PA6 PB0 PA4 PA5 5V GND FAN1 -HEO+-BED+-PWR+ Github: https://github.com/makerbase-mks FaceBooK: https://www.facebook.com/Makerbase.mks/ Makerbase Sheet: File: MKS Robin E3.kicad_pcb Title: MKS Robin E3 Size: A4 Date: 2021-03-26 Rev: V1.1_003 KiCad E.D.A. kicad (5.1.4)-1 ld: 1/1