1. Use multi-meter to check the DC ±30V and ±50 terminal.

DC +30V terminal showed on the multi-meter is about 31V.



DC -30V terminal showed on the multi-meter is about -31V.



DC +50V terminal showed on the multi-meter is about +59V.



DC -50V terminal showed on the multi-meter is about -57V.

