Panel 4412356 Date Printed: 03/12/2013 13:49

Standardized Work Sheet



Operation Cycle Time: 0

Sheet: 1

Bill of Materials

	al By:					0
	Approv					
Doforono	Qty Designator					
	Qty	4 000	1.000	4.000	2.000	
	Description		Honsing	Cap Screw	Flat Washer	
	Rev					
	Part Number	111000	888///	456789	323232	

Steps


	_			Value	Waste	Value Waste Cumulativ
Figure(s)	Sed	Steps	Symbol	Time	Time	Time
	\bigcirc	General Requirements	%	0.00	00.0	0
		Verify you read all required information	V			
	3	Specifications - Changed Specs 1-22-13	5	0.00	00.0	0
	3	Stage Shipping Locks	5	0.00	00.0	0
	4	Linear Stage Prep - Test Changes Made	,			
1 2)	on a step in a work order 1-22-13 dew	7	0.00	0.00	0
	(2)	Clip Center Limit - Version Note test				
က)	2:12 on 1-22	7	0.00	0.00	0
4 5	9	Solder pins	5	0.00	00.00	0
	(2)	Center Limit Quality Check	99	0.00	00'0	0

∔ C	Flow
(<u>%</u>)	Scope
©	Objective
	Environmental
9	Quality
V	Alert
5	Instruction
STOP	Safety
lcon:	Meaning:



Remove Cover Remove Cover





Center Limit Switch Cable
Center Limit Switch Cable

5



7

Sequence

Admin

Sequence Admin

Sequence Admin

_

12/7/2012

12/7/2012

3/12/2013

Approval Date:

Version:

 α

Operation: Panel General Requirements


Part: 4412356 - Panel

Limit Switch Cover Removed
Limit Switch Cover Removed

4



Secure Pins w/Wires



Solder Crimp Pins Solder Crimp Pins

Standardized Work Sheet



Part: 4412356 - Panel Operation: Panel

Operation Cycle Time: 0

12/7/2012

12/7/2012

3/12/2013

Approval Date:

Version:

 α

Sequence Admin

Sednence

Sequence Admin

Admin

Sheet: 1


Bill of Materials

Reference Approval By: Designator 8.000 8.000 Qty Flat Washer Description Cap Screw Rev Part Number 456789 323232

Steps


				Value	Waste	Value Waste Cumulative
Figure(s)	Sed	Steps	Symbol Time	Time	Time	Time
1	(J)	Clip other two wires	V	00.00	00.00	0
2	(2)	Strip Insulation	V	00.00	00.00	0
3 4	(3)	White Wires	S	0.00 0.00	0.00	0
9 9	4	4) Mark Bottom Cable	1	0.00 0.00	00.00	0

:uc	STOP	5	•	8	((2)	8	∔ C
eaning:	Safety	Instruction	Alert	Quality	Environmental	Objective	Scope	Flow



Cut Limit Switch Wires
Cut Limit Switch Wires

က




Cut off white wire

2



Identify Bottom Limit Switch




7

_

Strip Insulation exposing 3 wires
Strip Insulation exposing 3 wires





Remove Cover

9



Mark Cable Mark Cable

Standardized Work Sheet



Part: 4412356 - Panel

Operation: Panel


Version:

Approval Date:

Steps

•							Approval Date:
				1/-1	11/1-11		
				value	waste	value waste Cumulative Approval By:	Approval By:
Figure(s) Seq	Sed	Steps	Symbol		Time	Time	
			•				
_	(S)	Solder Wire Pairs	5	0.00	0.00	0	
·	C	-		000	0	(
7	9	Connector plug	3	0.00	0.00	0	
2 4	(4)			000		d	
F 6)	Urimp Pins - Needed to be ,	3	0.00	0.00	U	
	<u></u>	Soldor without	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	000	000	C	
	9		3	0.00	0.00	U	
			•				
v	<u></u>	Wotor Mount Plate	5	0.00	0.00	0	

←C	Flow
8	Scope
(2)	Objective
	Environmental Objective
9	Quality
	Alert
5	Instruction
STOP	Safety
lcon:	Meaning:



Solder Twisted Blue Wires
Solder Twisted Blue Wires





Install Male Pins Install Male Pins





Plate Orientation
Plate Orientation



12/7/2012


12/7/2012

3/12/2013

 $^{\circ}$

Operation Cycle Time: 0

Sheet: 2



Molex Molex

4



Installed crimp Pins