STANDARD OPERATING PROCEDURE OF PULL STRENGTH VF-B04

Lab /SOP/ 39




Tensile testing machine with chart recorder
Razor or sharp knife.
Steel scale or calipers capable of measuring



Clamp for eyelet pull strength test



Remove the outsole from upper.
Separate the test sample extracted from lateral side and from medial side. To avoid the upper touching the tensile machine during testing.



Zero and calibrate the testing machine.




Insert the shoe lace into the eyelet.
Clamp the shoe lace at one jaw and the upper (eye-stay) at the other jaw.
Ensure that the samples are aligned.



Set the speed at 100 mm/min.
Operate the tensile testing machine
As soon as any failure occurs, record the corresponding force.



Record the maximum force to cause failure.



Make report
Maximum force at failure in kgf
Type of failure
Any deviations from this procedure.

Prepared by	Approved by	REVISION		DATE	