VF Asia Footwear Laboratory Testing Manual

Test Method for PVC Identification Test	**Test method # VF- E15** **Page 1 of 1**
Date Issued : May 27, 2008 **Revision # :**	**Created by : Nila Babia Erazo / Chris Adam**

PURPOSE AND SCOPE: To identify the presence of PVC in plastics.

REFERENCE:

EQUIPMENT AND MATERIAL:

1. Copper wire
2. Bunsen burner or other equipment which can provide a continuous steady flame.
3. Plastics

SAMPLE PREPARATION:

1) Condition the sample for at least 24 hours at standard laboratory environment at 23.0±2.0˚C temperature and 55 ±10 % Relative Humidity.
2) Die or hand cut a sample of the plastic test material which has a length of at least 2 cm.

REPETITIONS: Test one (1) sample per material**.**

TEST PREOCEDURE:

1. Heat the copper wire until it becomes red (glowing) hot.
2. Place the copper wire onto the test sample such that a small amount of the test sample melts and adheres to the copper wire.
3. Hold the copper wire over the flame again.
4. If the color of the flame becomes green, the specimen contains PVC.

REPORT: The presence or absence of PVC in the plastic.