VF Asia Footwear Laboratory Testing Manual

Test Method for Blooming Test	Test method # VF- E17 Page 1 of 1
Date Issued : March 14 , 2016 Revision # : 1 Reason for revision : Lowered the temperature from 70 ° C to 60 ° C	Created by : Nila Babia Erazo

PURPOSE AND SCOPE: To measure the appearance of blooming on certain material as a result of exposure to heat and relative humidity for a specified time period.

REFERENCE: None

EQUIPMENT AND MATERIAL:

1. Air-circulating oven, capable of maintaining temperature of 60 ± 1ºC and relative humidity at 95 ± 1%.
2. Rubber outsole and components that likely will bloom.

SAMPLE PREPARATION:

Condition the test samples at 23+/-2ºC and 55+/-10% relative humidity for 24 hours prior to testing (unless otherwise specified) .

REPETITIONS: Test one (1) sample per material combination.

TEST PROCEDURE:

1. Place the test materials in an oven at 60 ± 1ºC for 7 days at 95 % relative humidity
2. After 7 days, remove the test material from the oven.
3. Let it cool down for at least 30 minutes at standard laboratory room temperature.
4. Check appearance of blooming or white deposit on the surface.

REPORT: Appearance of blooming.