VF Asia Footwear Laboratory Testing Manual

Test Method for Non Marking Test	Test method # VF- E21 REF # : TM-R 057 Page 1 of 2
Date Issued : July , 2014 Revision # : 1 Reason for revision: Added TBL test method, option 2.	Created by : Nila Babia Erazo / Chris Adam

PURPOSE AND SCOPE: To check if the outsole or any component has marking tendency when in contact with foot and floor surfaces made of wood, mason and PVC tiles.

REFERENCE: NONE

EQUIPMENT AND MATERIALS:

1. White paper
2. 1 ft^2 vinyl tiles
3. Paper towels
4. Cleaning solution
5. Rubber outsole or shoe to be tested usually black or dark colored

SAMPLE PREPARATION:

Condition the test sample at 23 ± 2°C and 55 ± 10 % RH for at least 4 hours prior to testing , unless otherwise specified.

REPETITIONS: Test one (1) sample per rubber outsole or material component.

TEST PROCEDURE:

Testing shall be conducted in a standard laboratory environment of 23 ± 2°C and 55 ± 10 % RH.

Option 1: Using white paper

1. Hold the outsole firmly and scrape it on the white paper
2. Check surface of the white paper if there is sign of marking

REPORT: Marking or Non marking

Test Method for Non Marking Test	Test method # VF- E21 REF # : TM-R 057 Page 2 of 2
Date Issued : July , 2014 Revision # : 1 Reason for revision: Added TBL test method, option 2.	Created by : Nila Babia Erazo / Chris Adam

Option 2: Using Vinyl Tiles:

1. Clean the 1 ft^2 vinyl tile using a paper towel and the cleaning solution.
2. Firmly holding the shoe, rub the edge of the heel across the tile.
3. Rate the marking according to the rating scale found in **Table 1.**
4. If a marking is present, rub it with a dry paper towel.
5. Rate the marking after rubbing with a dry paper towel.
6. An outsole shall be considered non-marking only when the mark is assigned a rating of “None” or “Slight” after rubbing with a dry paper towel.

Table 1. Rating scale for outsole marking.

Rating	Rating Description
None	Nothing visible
Slight	Scuffing, no color transfer
Moderate	Some marking with some color transfer
Severe	Heavy marking with strong color transfer

REPORT:

1. Marking or Non marking
2. Rating before and after rubbing the marking with a paper towel
3. Deviations from this test procedure.