VF-E28 Glow in the dark

Test Method for Glow in the dark	Test method #: VF-E28
Date Issued: August 2024 Revision #:	Reason for Revisions: New launch

PURPOSE AND SCOPE: To measure glow in dark material's durability.

REFERENCE: NA

EQUIPMENT AND MATERIAL:

1. Dark Room
2. Light Box – D65 & CWF lamp

SAMPLE PREPARATION:

Condition the sample for 24 hours at standard laboratory environment @ 23.0±2.0˚C Temperature and 55 ±10 % Relative Humidity.

Glow in the dark material ex: Leather, synthetic leather, fabric, Rubber Outsole

REPETITIONS: Test two (2) samples per material.

TEST PROCEDURE:

Test should be conducted at standard laboratory conditions @ 23.0±2.0˚C temperature and 55 ±10 % Relative Humidity.

1. Place the color light box in a dark room.
2. Keep the specimen in the dark room at least 24 hours before test.
3. Expose original specimen just under D65 light for 1 min, then turn off the light and immediately evaluate if the specimen still glows; re-evaluate the specimen after leaving it in the dark room for 10 min.
4. Expose another piece of original specimen just under CWF (Cool White Fluorescent) light for 1 min. then turn off the light and immediately evaluate if the specimen still glows; re-evaluate the specimen after leaving it in the dark room for 10 min.
5. Repeat Procedure 2, 3 and 4 after care label washing treatment (3 Machine wash or 3 Hand wash or 1 Dry-cleaning)

Evaluation:

VF-E28 Glow in the dark

Evaluate if the original and washed specimen either “Still glow” or “No glow” after the exposure of D65 (Daylight) and CWF (Cool White Fluorescent) light separately.

TEST REPORT:

1, If all evaluation is “still glow” the results is “PASS” for the light source

2, Any one evaluation of “No glow” occurs, the result is “FAIL” for the light source