

TCU Utilization Increases with Larger K  
MxN=64x64, fp8, A/B 0%/0% sparse, Q=4, step sizes: 2x16, 4x8

