



MAINTENANCE ALERT - Bearing 16007 #11 reached end of life - MR200 stopped | تنبيه صيانة - Bearing 16007

MR200 رقم 11 بلغ نهاية عمره - توقفت

1 message

MR200 Production Line Monitoring System <GhayathAlali2003@gmail.com> Fri, 28 Aug 2026 at 5:29 pm  
To: ghayathahmad2002@gmail.com

MAINTENANCE ALERT

MR200 Slicing Machine

Automatic stop · Friday 28 August 2026, 17:28:37

Dear Production Line Maintenance Department,

The machine has automatically stopped because the following component has reached its expected life.

**Bearing 16007** at machine position **#11** consumed **2,197,000,016 revolutions** against a rated life of 2,197,000,000 revolutions (100.00% of its expected life).


FAILED ELEMENT

|                               |                                      |
|-------------------------------|--------------------------------------|
| Element                       | Bearing 16007 #11                    |
| Element Type                  | Bearing 16007                        |
| Identification / Order Number | #11                                  |
| Machine Position              | Bottom cutting shaft - 16007 bearing |
| Default Life                  | 2,197,000,000 revolutions            |
| Consumed Life at Failure      | 2,197,000,016 revolutions            |
| Remaining Life                | 0 revolutions                        |
| Life Used                     | 100.00%                              |
| Element Price                 | \$31.00                              |



100.00% of expected life consumed

COMPONENT REFERENCE PICTURE



MACHINE STATUS AT FAILURE

|                            |                                                        |
|----------------------------|--------------------------------------------------------|
| Machine State              | STOPPED - automatic maintenance stop                   |
| Production / Cutting State | Cutting operation interrupted by end-of-life detection |

|                                          |                         |
|------------------------------------------|-------------------------|
| Machine Runtime                          | 00:00:14                |
| Production Quantity Since Machine Start  | 0.0155 m³               |
| Electricity Consumed Since Machine Start | 0.0006 kWh              |
| Current Machine Speed                    | 3492.3 RPM              |
| Wood Being Processed                     | Lignamon 783 (Hardwood) |

### RECENT MAINTENANCE OF FAILED ELEMENT (LAST 30 DAYS)

Number of maintenance operations in the last 30 days: **4**

| MAINTENANCE DATE | DONE BY | COST    | ELEMENT PRICE | STOPPING TIME COST |
|------------------|---------|---------|---------------|--------------------|
| 2026-08-28 17:27 | Mazen   | \$0.00  | \$31.00       | \$0.00             |
| 2026-08-28 16:28 | Jamal   | \$10.00 | \$31.00       | \$20.00            |
| 2026-08-28 16:10 | Maher   | \$40.00 | \$31.00       | \$60.00            |
| 2026-08-28 16:03 | Johen   | \$10.00 | \$31.00       | \$30.00            |

### OTHER ELEMENTS APPROACHING FAILURE

Elements whose consumed life has reached 80.00% or more of their expected life.

No other element has passed the 80.00% warning threshold.

### LAST GENERAL MACHINE MAINTENANCE

|                       |                   |
|-----------------------|-------------------|
| Last Maintenance Date | 2026-08-28 17:27  |
| Element(s) Maintained | Bearing 16007 #11 |
| Done By               | Mazen             |
| Maintenance Cost      | \$0.00            |
| Element Price         | \$31.00           |
| Stopping Time Cost    | \$0.00            |

### ATTACHMENTS

- Failed element picture
- Element catalogue — SKF\_16007\_Deep\_Groove\_Ball\_Bearing.pdf

The machine has been stopped automatically to allow the maintenance department to inspect the affected component. Production cannot resume safely until the element is inspected or replaced.

تنبيه صيانة

آلة التقطيع MR200

إيقاف تلقائي · 17:28:37 28-08-2026

إلى قسم صيانة خط الإنتاج المحترم،

توقفت الآلة تلقائياً لأن العنصر التالي قد بلغ نهاية عمره المتوقع. **Bearing 16007** في الموقع رقم **11** استهلك **2,197,000,016** دورة من أصل عمر افتراضي مقداره 2,197,000,000 دورة (أي ما نسبته 100.00% من عمره المتوقع).

العنصر المعطل

|                                |                                |
|--------------------------------|--------------------------------|
| العنصر                         | Bearing 16007 – 11             |
| نوع العنصر                     | Bearing 16007                  |
| رقم التعريف / الترتيب في الآلة | 11                             |
| الموقع في الآلة                | عمود القطع السفلي – محمل 16007 |
| العمر الافتراضي                | 2,197,000,000 دورة             |
| العمر المستهلك عند العطل       | 2,197,000,016 دورة             |
| العمر المتبقي                  | 0 دورة                         |
| نسبة العمر المستهلك            | 100.00%                        |
| سعر العنصر                     | \$31.00                        |

حالة الآلة عند حدوث العطل

|                              |                                               |
|------------------------------|-----------------------------------------------|
| حالة الآلة                   | متوقفة – إيقاف تلقائي للصيانة                 |
| حالة الإنتاج / القطع         | توقفت عملية القطع بسبب بلوغ العنصر نهاية عمره |
| مدة تشغيل الآلة              | 00:00:14                                      |
| كمية الإنتاج منذ بدء التشغيل | 0.0155 م <sup>3</sup>                         |
|                              |                                               |

|                                             |                         |
|---------------------------------------------|-------------------------|
| الطاقة الكهربائية المستهلكة منذ بدء التشغيل | 0.0006 ك.و.س            |
| سرعة الآلة الحالية                          | 3492.3 دورة/دقيقة       |
| نوع الخشب قيد المعالجة                      | Lignamon 783 (Hardwood) |

### صيانة العنصر المعطل خلال آخر 30 يوماً

عدد عمليات الصيانة خلال آخر 30 يوماً: 4

| تاريخ الصيانة    | نُفذت بواسطة | تكلفة الصيانة | سعر العنصر | تكلفة زمن التوقف |
|------------------|--------------|---------------|------------|------------------|
| 17:27 2026-08-28 | Mazen        | \$0.00        | \$31.00    | \$0.00           |
| 16:28 2026-08-28 | Jamal        | \$10.00       | \$31.00    | \$20.00          |
| 16:10 2026-08-28 | Maher        | \$40.00       | \$31.00    | \$60.00          |
| 16:03 2026-08-28 | Johen        | \$10.00       | \$31.00    | \$30.00          |

### عناصر أخرى تقترب من نهاية عمرها

العناصر التي بلغ عمرها المستهلك 80.00% أو أكثر من عمرها المتوقع.

لا يوجد عنصر آخر تجاوز حد التحذير البالغ 80.00%.

### آخر صيانة عامة للآلة

|                         |                    |
|-------------------------|--------------------|
| تاريخ آخر صيانة         | 17:27 2026-08-28   |
| العنصر الذي تمت صيانتته | Bearing 16007 – 11 |
| نُفذت بواسطة            | Mazen              |
| تكلفة الصيانة           | \$0.00             |
| سعر العنصر              | \$31.00            |
| تكلفة زمن التوقف        | \$0.00             |

### المرفقات

- صورة العنصر المعطل
- كتالوج العنصر – SKF\_16007\_Deep\_Groove\_Ball\_Bearing.pdf

تم إيقاف الآلة تلقائياً لتمكين قسم الصيانة من فحص العنصر المتأثر. لا يمكن استئناف الإنتاج بأمان قبل فحص العنصر أو استبداله.

مع خالص التحية،

أُنشئت هذه الرسالة تلقائياً بواسطة نظام الصيانة التنبؤية للآلة MR200. الرجاء عدم الرد عليها.

---

## 2 attachments



**16007-4.png**

96 KB



**SKF\_16007\_Deep\_Groove\_Ball\_Bearing.pdf**

1.2 MB