



<- put solder joint here for polarity inversion (motor valves)

## Section Control V1.1

Sect 0 or Speed Sensor

NPN OV PNP +12V

Sect 2

AgOpenGPS succession

Main Valve





