Bubba Gump Las Olas:

Problem: Oven in line is noisy.

Notes: Check if motor is making noise, check fan blade.

Kitchen Line: Left Oven Motor Specs1/2 HP 115V Motor RPM 1725


• AMB 40 C° Maximum ambient temperature = 40 C°

• **INS B** Insulation class B, allowable temperature rise = 130 C°

• Motor rated for 170 C° / 338 F°

Notes: Motor is quite new and temp is within spec, should not be the problem.





Motor behind oven in line and specs

Temp Reference:

http://toshont.com/wp-content/uploads/2017/06/Motor-Temperature-Rise.pdf http://www.elongo.com/pdfs/MotorNameplate990519.pdf Kitchen Line: Left Oven Motor Measurements

• Length of motor= 7 ½"

• Diameter = 5 ½"



Note: Motor may need to be replaced, motor was removed from oven and measured.

Kitchen Line: Left Oven Motor Fan Measurements

- Axis Diameter = ½"
- Diameter = 6 \(\frac{3}{8} \)"
- Depth = 2 ½"





Blower inside of oven

Notes:

Blower does not touch metal behind or in front.

Motor might be making the noise and not the blade.


Metal frame in front of blade is missing screw on bottom, frame is loose (not the source of the noise).

Blade to be replaced first.

Solution:

Bought Driver blower off Grainger website, replaced old one. No more noise coming off of oven.

Direct Drive Blower Wheels



Blower Wheel from Grainger costs \$84.73 with shipping included.

https://www.grainger.com/category/direct-drive-blower-wheels/blower-accessories/industrial-blowers-and-accessories/ventilation-equipment-and-supplies/hvac-and-refrigeration/ecatalog/N-yma#nav=%2Fcategory%2Fdirect-drive-blower-wheels%2Fblower-accessories%2Findustrial-blowers-and-accessories%2Fventilation-equipment-and-supplies%2Fhvac-and-refrigeration%2Fecatalog%2FN-ymaZ1z0o4plZ1z0nz67Z1z0nz65