

QUALITY AUTO #50
8402 W. COLFAX
LAKEWOOD, CO 80215
Phone (303) 232-2570

Since 1974

Invoice	s16610
Date	04-08-18
Store	QA50
Type	Delivery
Printed	040818 12:14
Customer ID	7193069606

Bill to

MATTHEW BAYER
573 CR 356
WEST CLIFF, CO 81252

Ship to

MATTHEW BAYER
573 CR 356
WEST CLIFF, CO 81252

Warehouse	P/O Number	Delivery Date	Terms	Sold At		Bill to Phones	Ship to Phones
QA50		04-08-18		QA50	Home	(719) 306-9606	(719) 306-9606
Salesperson		Salesperson			Work		
5421 ANDREAS J. GONZALES					Cell		
01 CHEVY TAHOE							

Item Number	Description	Brand	U/M	Order	Ship	List Price	Extended
KDCHD262U	~KENWOOD HD/USB/CD/AUX 50X4	KEN	EA	1	0	99.99	99.99
INSTADECK	STANDARD INSTALL INCLUDED	FRE	EA	1	0	1.00	1.00
99-4544	GM MULTI KIT, 82-96 W/HARDWARE	MET	EA	1	0	24.99	24.99
40-GM10	AFTERMKT RADIO - GM ANT W/MINI	MET	EA	1	0	19.99	19.99
70-1858	GM 88+, 21 PIN	MET	EA	1	0	19.99	19.99
SHOP	NECESSARY SHOP SUPPLIES	FRE	EA	1	0	8.50	8.50
WARNING	WAIVES FREE EXCHANGE!	FRE	EA	1	0		
VS 5783 Auth=09704C Credit Card				187.47	Sales Amount		174.46
					Sales Tax		13.01
					Freight		.00
					Total		187.47

I DECLINE THE OPTIONAL IN STORE REPLACEMENT SERVICE PLAN. I WILL SEEK WARRANTY REPAIRS AT A FACTORY REPAIR CENTER, IF NEEDED.

CUSTOMER INITIALS: _____

I AGREE TO TERMS AND CONDITIONS ON REVERSE, AND SEPARATE VIDEO LIABILITY RELEASE. ALL SALES ARE FINAL NO REFUNDS. ALL PARTS AND PRODUCT PACKAGING REQUIRED FOR EXCHANGES. WILL INCUR CHARGES FOR MISSING PARTS

PURCHASER SIGNATURE _____

Nationally Honored - Car Audio Retailer of the Year. Visit us online at Qualityautosound.com

2001 Chevy Tahoe LT

↳ Purchased from Dellenbach motors in ~~Atlanta~~ Ft Collins, Co. in
June 2017. 105,019 miles

November 2017 - 107431 miles

- added 1 qt synthetic SAE 5W30 oil. Oil light came on indicating low oil. Wishing? Burning? Leaking?
- Replaced driver side windshield wiper

B&D AUTOMOTIVE

601 Main St
Silver Cliff, CO 81252
Phone 719-783-4222 Fax 719-783-4222
Experience Eliminates Experiments

INVOICE**24190****INVOICE****BAYER, MATT**

1094 CR 260

Westcliffe CO 81252

Home 719-306-9606

Work Completed 05/17/2019

Date: 05/17/2019

2001 Chevrolet - Tahoe - 5.3L V8 (325CI) VIN(T)

Lic # AHO550

Odometer In 129531

VIN # 1GNEK13T4 1R129987

Part Description / Number	Qty	Sale	Ext	Labor Description	Hours	Ext
BRAKE PADS PREM W/HARDWARE PMD834H	1.00	79.98	79.98	REPLACE REAR DISC PADS AND REPLACE ROTORS	1.20	96.00
ROTOR 48880165 Shop Supplies	2.00	80.84	161.68	REPLACE REAR BRAKE PAD LININGS AND REPLACE REAR BRAKE DISC ROTORS CLEAN AND LUBRICATE BRAKE CALIPERS AND SLIDE MECHANISMS CHECK AND FILL BRAKE FLUID BLEED AIR FROM SYSTEM ROAD TEST VEHICLE.		
			6.00			

Is changed Front Brake Pads,
N/A? No Rotor change for
Front 129531

[Payments - Check (#275) - \$360.75]

Find us on facebook-B&D Automotive

An express mechanic's lien is hereby acknowledged on the above vehicle to secure the amount of repairs thereto. Warranty on parts and labor is 12 months or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Find us on facebook-B&D Automotive

Vehicle Received 5/17/2019

Customer Number : 756

Signature _____

Date _____

Labor:	96.00
Parts:	247.66
Sub:	343.66
Tax:	17.09
Total:	\$360.75
Bal Due:	\$0.00

Jim's Tire Service
1005 S 9th St
Canon City, CO 81212
(719) 275-1576

TAHOE

Jim's Tire Service
P.O. BOX 1005 1005 Sth 9th ST
Canon City, CO 81212
(719) 275-1576

INVOICE 1-333187
S-06/04/19 E-06/06/19
S-08:24 E-07:50

Page: 1
NONSIG: 169671

* * * I N V O I C E * * *

Sold: MATT BAYER

WESTCLIFFE, CO 81252
H-719-306-9606

Veh: 01 CHEVY TAHOE
Lic: AHO-550
Mil: /131072
Emp: 126/128
PO#:

Slsn Mech	Part #	QTY Description	Price	F.E.T.	Total
			89.95	0.00	89.95
		1.00 .50020 4X4 COMP ALIGNMENT	5.00	0.00	5.00
126 128	ALI004	1.00 .93004 SHOP SUPPLIES	179.00	0.00	716.00
126 128	MEC0001	4.00 .400225 BILSTIEN	12.00	0.00	48.00
126 128	SHK0045	4.00 .40035 INSTALL SHOCK	7.50	0.00	67.50
126 128	SHK007	9.00 .30040 COMP SPIN BALANCE			
126 128	PAS007				

☒ Changed Fuel Filter NAPA GOLD
☒ Oil change Napa Gold 1042
☒ Cleaned Air filter
131072

"SECTION 30-20-1403, COLORADO REVISED STATUTES, REQUIRES
RETAILERS TO COLLECT A WASTE FEE SET BY THE SOLID AND
HAZARDOUS WASTE COMMISSION ON THE SALE OF EACH NEW MOTOR
VEHICLE TIRE AND EACH NEW TRAILER TIRE:"

					Subtotal	926.45
Cash	Check	Credit Card	Charge	Sales Tax @ 8.400%	60.14	
\$0.00	\$0.00	\$986.59	\$0.00		Total	986.59

Tire Service, Inc.

P.O. Box 1005 - South 9th
Canon City, CO 81212

Phone Number: 719-275-1576

MATT BAYER

Date:

6/4/2019 2:54 PM

Vehicle No:

AHO-550

VIN

Odometer:

131,072

Technician:

Order No.:

VEHICLE ALIGNMENT REPORT

CHEVROLET TRUCKS, 2001, TAHOE K15

Primary Angles

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	2.80°	2.50°	4.50°	3.06°
		Right	3.44°	3.50°	5.50°	3.72°
	Camber	Left	-0.12°	-0.25°	0.75°	0.25°
		Right	0.18°	-0.25°	0.75°	0.14°
	Toe	Left	1/32"	-1/32"	1/16"	1/16"
		Right	0"	-1/32"	1/16"	1/16"
Total		1/32"	-1/16"	5/32"	1/8"	
Rear	Camber	Left	-0.33°	----	----	-0.31°
		Right	-0.31°	----	----	-0.36°
	Toe	Left	1/32"	----	----	1/16"
		Right	1/32"	----	----	0"
		Total	1/16"	----	----	1/16"
	Thrust Angle		0.00°			

Secondary Angles

			Initial	Specifications		Final
				Min.	Max.	
SAI	Left		10.61°	---	---	10.45°
	Right		10.62°	---	---	10.70°
Included Angle	Left		10.49°	---	---	10.70°
	Right		10.80°	---	---	10.84°
Toe Out On Turns	Left		---	---	---	---
	Right		---	---	---	---
Maximum Turns	Left		---	---	---	---
	Right		---	---	---	---
Toe Curve Change	Left		---	---	---	---
	Right		---	---	---	---
Setback	Front		0.01"	---	---	0.10"
	Rear		-0.09"	---	---	-0.11"
Track Width Diff.			-1.25"			-1.12"
Wheel Base Diff.			0.10"			0.21"
Front Ride Height	Left		---	4.30"	4.80"	---
	Right		---	4.30"	4.80"	---
Rear Ride Height	Left		---	---	---	---
	Right		---	---	---	---
Frame Angle						0.00°

Three Dimensional Wheel Alignment

Clean Touch Detailing
Silver Cliff, Co
719-285-3687
Nicholas Grossardt

INVOICE

Bill To:

Matt Bayer
2001 gm Tahoe

Invoice# inv1251
Invoice Date 8/16/2021
Due Date 8/16/2021

Item Description	Qty	Rate	Amount
Oil filters	2	21.65	43.30
Air Filter	1	54.89	54.89
Fuel Filter	1	41.28	41.28
PCV valve	1	19.21	19.21
GM. OE Spark Plug	8	14.33	114.64
Oil 5W30 bulk oil	16	7.99	127.84
BG MOA	1	24.99	24.99
BG EPR	1	28.35	28.35
Cleaner	4	7.99	31.96
Spark Plug Wire Set	1	120	120.00
Cabin air filter	1	57.45	57.45
DAYCO serp belt	1	82.77	82.77
DAYCO belt for AC.	1	48.65	48.65
Rear caliper's	2	212.12	424.24
Rear Rotors	2	125.44	250.88
Brake Pads Rear	1	190.89	190.89
Drain plug	1	6.25	6.25

Item Description	Qty	Rate	Amount
w w fluid	1	1.45	1.45
Idler Pully	1	24.85	24.85
ATF fluid	1	10.25	10.25
Wind shield wipers	2	26.95	53.90
	1	0	0.00
Sub total			1758.04
(7.00%)			123.06
Total			\$1881.10

Terms and Conditions

THANK YOU!!

Please Make Payments Out To Nicholas Grossardt
grossardtn@gmail.com

INVOICE

Clean Touch Detailing
Silver Cliff, Co
719-285-3687
Nicholas Grossardt

Bill To:

Matt Bayer
2000 GM suburban and 2001 GM tahoe

Invoice# inv1253
Invoice Date 8/16/2021
Due Date 8/16/2021

Item Description	Qty	Rate	Amount
LOF WITH ENGINE FLUSH AND BG EPR AND MOA	2	100	200.00
TUNE UP FULL CLEAN WITH BG AIR INDUCTION KIT. PLUGS,WIRES,PCV VALVE,	3	100	300.00
REAR BRAKES ROTORS,PADS,CALIPERS, FLUSH BRAKE FLUID.	4	100	400.00
CABIN AIR FILTER REPLACEMENT CLEAN AND DISINFECT	0.85	100	85.00
REMOVE AND REPLACE SHOCKS ON 2000 SUBURBAN	2	100	200.00
CLEANING AND MISS TIME AIR BOX AND VENTS, CLEAN, INSTALED SCREEN FOR RODENTS.	1	100	100.00
Sub total			1285.00
Total			\$1285.00

Terms and Conditions

THANK YOU!!

Please Make Payments **Out To Nicholas Grossardt**

*TOTAL all 3988.35
Paid 2500.00
Bal owed 1488.35*

AUSTIN AUTOMOTIVE LLC
2625 E MAIN ST
CANON CITY, CO 81212
719 719-2755055

AUSTIN AUTOMOTIVE

2625 EAST MAIN STREET
CANON CITY CO, 81212

Phone: 719-275-5055

VISIT US AT WWW.AUSTINAUTOMOTIVE.COM
MON - THURS 7:30AM - 5:30PM / FRI 7:30AM - 4:30PM

10/09/2024 2:26:37 PM

Repair Order #

41389

10/09/2024

14:39:09

Credit Sale

Transaction #: 6
Card Type: Visa
Account: *****4619
Entry: Manual
Amount: USD\$479.11
Ref. Number: 610908397
HREF: 610908397
Global UID: 1240071172202410091439093989
Auth. Code: 08135D
Batch #: 83
Response: Transaction approved 757Jason

CUSTOMER COPY

Thank You!

Vehicle Time In: 10/7/2024 2:35:08PM

Vehicle Time Out: 10/7/2024 3:35:08PM

2001 Chevrolet Tahoe

Odometer In: 167529

Odometer Out: 167529

License: APW-W74 CO

VIN: 1GNEK13T41R129987

Eng: 5.3 L 325 CID V8

CONCERN AND CAUSE

CUSTOMER STATES :

LOF, INSPECTION, HEATER CORE QUICK IS DISCONNECT, HORN FUSE KEEPS BLOWING RIGHT AFTER BEING REPLACED, RUMBLING SOUND FRONT END - 50 MPH. REPLACED BATTERY - NO ROTATE

WORK PERFORMED:

Performed oil change - replaced battery and both front sway bar links was unable to diagnose horn at this time. Vehicle will need a coolant flush and at that time we will replace the heater hose tees. Technician said when he check horn operation it was working fine, fuse is still intact.

LUBE, OIL, AND FILTER CHANGE

DRAIN AND REFILL CRANKCASE WITH PREMIUM MOTOR OIL, REPLACE OIL FILTER. LUBRICATE CHASSIS WHERE APPLICABLE. INSPECT AIR AND CABIN FILTER, TOP OFF ALL FLUID LEVELS AND APPLY REMINDER STICKER

Labor: \$25.00

Parts: \$0.00

Sublet: \$0.00

Job Total: \$25.00

Multi Point LOF Inspection

PERFORM Multi Point LOF Inspection

Description

5W/30 Synthetic Blend Oil
Oil Filter - PROFORMER
Air Filter - PROFORMER

Quantity	Sale	Extended
6.00	\$3.99	\$23.94
1.00	\$5.12	\$5.12
1.00	\$21.86	\$21.86

Job Total: \$50.92

Labor: \$0.00

Parts: \$50.92

Sublet: \$0.00

BATTERY Remove & Replace

Includes: Test.

Description

Interstate Battery
Sway Bar Link Kit - Front

Quantity	Sale	Extended
1.00	\$205.17	\$205.17
1.00	\$64.08	\$64.08

Job Total: \$269.25

Labor: \$0.00

Parts: \$269.25

Sublet: \$0.00

STABILIZER BAR CONTROL LINK Remove & Replace

Labor: \$77.00

Parts: \$0.00

Sublet: \$0.00

Job Total: \$77.00

\$378 Coolant Flush
Heater Hose Connectors





AUSTIN AUTOMOTIVE

2625 EAST MAIN STREET
CANON CITY CO, 81212

Phone: 719-275-5055

VISIT US AT WWW.AUSTINAUTOMOTIVE.COM

MON - THURS 7:30AM - 5:30PM / FRI 7:30AM - 4:30PM

10/09/2024 2:26:37 PM

Repair Order #
41389

RY SIDE HEATING AND SOLAR

/KALEA BAYER

22 EDELWEISS DR

WESTCLIFFE CO, 81252

Cell 7193069606Matt ; Cell 7193715757Jason

Repair Order

2001 Chevrolet Tahoe

Odometer In: 167529

Odometer Out: 167529

License: APW-W74 CO

VIN: 1GNEK13T41R129987

Eng: 5.3 L 325 CID V8

Continued From Previous Page

Service Advisor: Cory B
Technician(s): Kyle S #55,

I consent to receiving text messages regarding your services, via automated technology, to the cell phone number you have on file. I acknowledge that I do not have to provide this consent to receive your services. Message and data rates may apply. Respond STOP to any message to cancel.

12 month, 12,000 mile warranty, whichever occurs first, is provided on all parts and labor unless otherwise specified. All warranty repairs must be performed at this facility. For warranty service outside a 25 mile radius from your original repairing location, contact the NAPA Auto Care Warranty Administrator at 800-452-NAPA (6272). For warranty service inside a 25 mile radius from your original repairing location, please contact your original location for service.

Labor Total:	\$102.00
Parts Total:	\$320.17
Shop Supplies:	\$25.00
HazMat:	\$2.95

Sub Total:	\$450.12
Tax Total:	\$28.99
Grand Total:	\$479.11
Balance Due:	\$479.11



SIGNATURE..... DATE.....





AUSTIN AUTOMOTIVE

2625 EAST MAIN STREET
CANON CITY CO, 81212
Phone: 719-275-5055

04/10/2025 5:31:33 PM

Repair Order #
43463

VISIT US AT WWW.AUSTINAUTOMOTIVE.COM
MON - THURS 7:30AM - 5:30PM / FRI 7:30AM - 4:30PM

04/16/2025 9
Credit Sale Visa
Transaction Manual
Card Type: \$650.14
Account: 688258275
Entry: 688258275
Amount:
Ref. Number: 61219580975
HREF: 01302G
Global UID: 215
Auth. Code: on approved
Batch #: 17193715757Jason
Responsible COPY
you!

WATERING AND SOLAR

2001 Chevrolet Tahoe

Odometer In: 171098

Odometer Out: 171098

License: APW-W74 CO

VIN: 1GNEK13T41R129987

Eng: 5.3 L 325 CID V8

Vehicle Time In: 4/3/2025 9:14:52AM

Vehicle Time Out: 4/3/2025 10:10:19AM

CONCERN AND CAUSE

CUSTOMER STATES :

ROTATIONAL CLICKING NOISE IN THE FRONT END CAN HEAR IF DRIVEN OVER 25MPH
LOF IF NEEDED

INSPECTION RESULTS:

Sway bar end link is missing on the passenger front
Transmission fluid is a little dark
Power steering fluid is dark
The driver side wheel was not torqued - the vehicle needs a hub assembly and the lug nuts.
Front axel seals are leaking bad - will need to be replaced

LUBE, OIL, AND FILTER CHANGE

DRAIN AND REFILL CRANKCASE WITH PREMIUM MOTOR OIL, REPLACE OIL FILTER. LUBRICATE CHASSIS WHERE APPLICABLE. INSPECT AIR AND CABIN FILTER , TOP OFF ALL FLUID LEVELS AND APPLY REMINDER STICKER

Labor: \$25.00

Parts: \$0.00

Sublet:\$0.00

Job Total: \$25.00


Multi Point LOF Inspection

PERFORM Multi Point LOF Inspection

Description	Quantity	Sale	Extended
5W/30 Synthetic Blend Oil	6.00	\$3.99	\$23.94
Oil Filter - PROFORMER	1.00	\$5.27	\$5.27
Labor: \$0.00	Parts: \$29.21	Sublet:\$0.00	Job Total: \$29.21

WHEEL HUB Remove & Replace

Description	Quantity	Sale	Extended
Wheel Bearing and Hub Assembly with Sensor - Front	1.00	\$283.65	\$283.65
Wheel Lug Nut	6.00	\$3.67	\$22.02
Suspension Stabilizer Bar Link Kit	1.00	\$67.64	\$67.64
Labor: \$231.00	Parts: \$373.31	Sublet:\$0.00	Job Total: \$604.31
Suspension Stabilizer Bar Link Kit			\$-67.64



AUSTIN AUTOMOTIVE

2625 EAST MAIN STREET
CANON CITY CO, 81212
Phone: 719-275-5055

VISIT US AT WWW.AUSTINAUTOMOTIVE.COM
MON - THURS 7:30AM - 5:30PM / FRI 7:30AM - 4:30PM

04/10/2025 5:31:33 PM

Repair Order #
43463

HEATING AND SOLAR

JAYER

SS DR

CO, 81252

J69606Matt ; Cell 7193715757Jason

2001 Chevrolet Tahoe

Odometer In: 171098

License: APW-W74 CO

Odometer Out: 171098

VIN: 1GNEK13T41R129987

Eng: 5.3 L 325 CID V8

air Order

Continued From Previous Page

Recommendations

- 10/09/2024 Work Order #41389, Sub Est 1 indicates a Coolant flush and heater connectors - \$378 was previously needed for your vehicle. Please reply for a detailed estimate and explanation.
- 04/10/2025 Work Order #43463, Sub Est 1 indicates a Front Axel Seals - \$584 was previously needed for your vehicle. Please reply for a detailed estimate and explanation.

Customer Authorization

4/7/25 11:27

Authorized By

COUNTRY SIDE
HEATING AND SOLAR

Previous Est.

\$ 646.16

Add'l Cost

\$ 646.16

Revised Est.

\$1,292.32

Written by: CB Initiated By: Customer Phone 719-306-9606 Matt

Service Advisor: Cory B

Technician(s): Jason C #46, ; Kyle S #55,

I consent to receiving text messages regarding your services, via automated technology, to the cell phone number you have on file. I acknowledge that I do not have to provide this consent to receive your services. Message and data rates may apply. Respond STOP to any message to cancel.

12 month, 12,000 mile warranty, whichever occurs first, is provided on all parts and labor unless otherwise specified. All warranty repairs must be performed at this facility. For warranty service outside a 25 mile radius from your original repairing location, contact the NAPA Auto Care Warranty Administrator at 800-452-NAPA (6272). For warranty service inside a 25 mile radius from your original repairing location, please contact your original location for service.

Labor Total: \$256.00
Parts Total: \$334.88

Shop Supplies: \$25.00
HazMat: \$2.95

Sub Total: \$618.83
Tax Total: \$31.31
Grand Total: \$650.14
Balance Due: \$650.14



SIGNATURE.....

DATE.....



AUSTIN AUTOMOTIVE LLC
2625 E MAIN ST
CANON CITY, CO 81212
719-275-5055

AUSTIN AUTOMOTIVE

2625 EAST MAIN STREET
CANON CITY CO, 81212

Phone: 719-275-5055

VISIT US AT WWW.AUSTINAUTOMOTIVE.COM

MON - THURS 7:30AM - 5:30PM / FRI 7:30AM - 4:30PM

10/28/2024 11:05:27 AM

Repair Order #

41617

10/29/2024

11:43:06

Credit Sale

Transaction #: 1
Card Type: Visa
Account: *****4619
Entry: Contactless
Amount: USD\$903.64
Ref. Number: 619340545
HREF: 619340545
Global UTD: 1240071172202410291143061663
Auth. Code: 096290
Batch #: 97
Response: Transaction approved
Mode: Issuer
AID: A0000000031010
TVR: 0000000000
IAD: 06021203A00000
TSI: 0000
ARC:
AC: 5217C7AC6517BFDC
ATC: 0070
APPN: CHASE VISA

7 SOLAR

7 Jason

2001 Chevrolet Tahoe

Odometer In: 167857

License: APW-W74 CO VIN: 1GNEK13T41R129987

Eng: 5.3 L 325 CID V8

Vehicle Time Out: 10/24/2024 10:02:55AM

CUSTOMER COPY

Thank You!

ESTCLIFFE OR CRIPPLE CREEK

Parts: \$0.00

Sublet: \$0.00

Charges: \$250.00

Job Total: \$250.00

Quantity	Sale	Extended
1.00	\$250.00	\$250.00

CONCERN AND CAUSE

CUSTOMER STATES :

TOW VEHICLE FROM WESTCLIFF

CHECK TRANSMISSION FLUID LEAK.

HVAC SYSTEM IS STUCK ON DEFROST - RPLEACED HVAC BLEND

CHECK RUMBLING NOISE IN FRONT END.

PREVIOUS TICKETS ATTACHED



INSPECTION RESULTS:

Found lower transmission cooler line blew out of radiator. The clip for the transmission cooler line was broken allowing fluid to leak out.

Replaced transmission clip and added 8qts of ATF.

Repaired HVAC unit actuator and performed manual calibration procedure. Found passenger compartment temperature sensor under headliner was not plugged in. Reconnected connector and cleared code, everything is now working as it should.

Rumbling noise was the front drive shafts replaced both front drive shaft u-joints. U-joint to transfer case was very bad.

Description	Quantity	Sale	Extended
Synthetic Universal ATF	8.00	\$5.99	\$47.92

Labor: \$77.00

Parts: \$47.92

Sublet: \$0.00

Job Total: \$124.92

AXLE SHAFT JOINT Remove & Replace

Description	Quantity	Sale	Extended
Universal Joint (U-Joint) - Front Driveshaft	2.00	\$47.99	\$95.98

Labor: \$369.60

Parts: \$95.98

Sublet: \$0.00

Job Total: \$465.58

HVAC DOOR ACTUATOR Remove & Replace





AUSTIN AUTOMOTIVE

2625 EAST MAIN STREET
CANON CITY CO, 81212

Phone: 719-275-5055

VISIT US AT WWW.AUSTINAUTOMOTIVE.COM

MON - THURS 7:30AM - 5:30PM / FRI 7:30AM - 4:30PM

10/28/2024 11:05:27 AM

Repair Order #

41617

SIDE HEATING AND SOLAR

KALEA BAYER

EDELWEISS DR

ESTCLIFFE CO, 81252

Cell 7193069606Matt ; Cell 7193715757Jason

2001 Chevrolet Tahoe

Odometer In: 167857

License: APW-W74 CO VIN: 1GNEK13T41R129987

Eng: 5.3 L 325 CID V8

Repair Order

Continued From Previous Page

Recommendations

10/09/2024 Work Order #41389, Sub Est 1 indicates a Coolant flush and heater connectors - \$378 was previously needed for your vehicle. Please reply for a detailed estimate and explanation.

Service Advisor: Cory B

Technician(s): Chad Austin,

I consent to receiving text messages regarding your services, via automated technology, to the cell phone number you have on file. I acknowledge that I do not have to provide this consent to receive your services. Message and data rates may apply. Respond **STOP** to any message to cancel.

12 month, 12,000 mile warranty, whichever occurs first, is provided on all parts and labor unless otherwise specified. All warranty repairs must be performed at this facility. For warranty service outside a 25 mile radius from your original repairing location, contact the NAPA Auto Care Warranty Administrator at 800-452-NAPA (6272). For warranty service inside a 25 mile radius from your original repairing location, please contact your original location for service.

Labor Total: \$446.60

Parts Total: \$143.90

Shop Supplies: \$25.00

HazMat: \$2.95

Charges: \$250.00

Sub Total: \$868.45

Tax Total: \$35.19

Grand Total: \$903.64

Balance Due: \$903.64



SIGNATURE..... DATE.....

