




1	2	3	4
---	---	---	---



Motor control

[illegible]

The diagram illustrates the power supply connections. On the left, a 3.3V source is connected to a 1x3 header, with pins labeled GND and V0. On the right, a battery symbol is connected to a 2-pin header labeled 'Battery connector', with a '-' sign indicating the negative terminal.