



2374_SIM767XM5A_M Firmware Release Note

LTE Module

SIMCom Wireless Solutions Limited

SIMCom Headquarters Building, Building 3, No. 289 Linhong
Road, Changning District, Shanghai P.R. China

Tel: 86-21-31575100

support@simcom.com

www.simcom.com

Document Title:	2374_SIM767XM5A_M Firmware Release Note
Latest FW Version:	2374B05_SIM767XM5A_M
Release Date:	2024.12.16
Status:	Released

GENERAL NOTES

SIMCom OFFERS THIS INFORMATION AS A SERVICE TO ITS CUSTOMERS, TO SUPPORT APPLICATION AND ENGINEERING EFFORTS THAT USE THE PRODUCTS DESIGNED BY SIMCom. THE INFORMATION PROVIDED IS BASED UPON REQUIREMENTS SPECIFICALLY PROVIDED TO SIMCom BY THE CUSTOMERS. SIMCom HAS NOT UNDERTAKEN ANY INDEPENDENT SEARCH FOR ADDITIONAL RELEVANT INFORMATION, INCLUDING ANY INFORMATION THAT MAY BE IN THE CUSTOMER'S POSSESSION. FURTHERMORE, SYSTEM VALIDATION OF THIS PRODUCT DESIGNED BY SIMCom WITHIN A LARGER ELECTRONIC SYSTEM REMAINS THE RESPONSIBILITY OF THE CUSTOMER OR THE CUSTOMER'S SYSTEM INTEGRATOR. ALL SPECIFICATIONS SUPPLIED HEREIN ARE SUBJECT TO CHANGE.

COPYRIGHT

THIS DOCUMENT CONTAINS PROPRIETARY TECHNICAL INFORMATION WHICH IS THE PROPERTY OF SIMCom WIRELESS SOLUTIONS LIMITED. COPYING, TO OTHERS AND USING THIS DOCUMENT, ARE FORBIDDEN WITHOUT EXPRESS AUTHORITY BY SIMCom. OFFENDERS ARE LIABLE TO THE PAYMENT OF INDEMNIFICATIONS. ALL RIGHTS RESERVED BY SIMCom IN THE PROPRIETARY TECHNICAL INFORMATION, INCLUDING BUT NOT LIMITED TO REGISTRATION GRANTING OF A PATENT, A UTILITY MODEL OR DESIGN. ALL SPECIFICATION SUPPLIED HEREIN ARE SUBJECT TO CHANGE WITHOUT NOTICE AT ANY TIME.

SIMCom Wireless Solutions Limited

SIMCom Headquarters Building, Building 3, No. 289 Linhong Road, Changning District, Shanghai P.R. China

Tel: +86 21 31575100

Email: simcom@simcom.com

For more information, please visit:

https://www.simcom.com/technical_files.html

For technical support, or to report documentation errors, please visit:

https://www.simcom.com/online_questions.html or email to: support@simcom.com

Copyright © 2024 SIMCom Wireless Solutions Limited All Rights Reserved.

Introduction

Purpose of the document

This Release Note introduces module firmware versions and briefly describes the benefits over preceding release. Also user can find differences compared to preceding release.

New Features: It lists features or AT commands which are newly developed compared to the preceding version.

Improved Features: It lists features or parameters that have been changed or improved compared to the preceding version.

Related documents

- [1] SIM767XX Series_AT Command Manual.docx
- [2] SIM767XX Series_FTP(S)_Application Note.docx
- [3] SIM767XX Series_HTTP(S)_Application Note.docx
- [4] SIM767XX Series_MQTT(S)_Application Note.docx
- [5] SIM767XX Series_SSL_Application Note.docx
- [6] SIM767XX Series_TCPIP_Application Note.docx
- [7] SIM767XX Series_CMUX_USER_GUIDE.docx
- [8] SIM767XX Series_FOTA_Application Note.docx
- [9] SIM767XX Series_GNSS_Application Note.docx
- [10] SIM767XX Series_Low Power Mode_Application Note.docx
- [11] SIM767XX Series_NETWORK_Application Note.docx
- [12] SIM767XX Series_Sleep Mode_Application Note.docx
- [13] SIM767XX Series_UART_Application Note.docx
- [14] SIM767XX Series_UIM HOT SWAP_Application Note.docx
- [15] SIM767XX Series_DUMP_TEST(win)_GRAB_GUIDE.docx
- [16] SIM767XX Series_EPAT_USER_GUIDE.docx
- [17] SIM767XX Series_FLASHTOOLS(linux)_BURN_GUIDE.docx
- [18] SIM767XX Series_FLASHTOOLS(win-usb)_BURN_GUIDE.docx
- [19] SIM767XX Series_FLASHTOOLS_USER_GUIDE.docx
- [20] SIM767XX Series_PORT_INSTRUCTION_GUIDE.docx
- [21] SIM767XX Series_Linux USB_Application Note.docx

Firmware Release Note

Version: 2374B05_SIM767XM5A_M

[New Features]

[Improved Features]

1. Fixed the issue: When the CCH receives more than 2K data at a time, the output to the serial port is not timely.
2. Fixed the issue: If the certificate file to be written is in the format of C:/ file name, an error occurs.
3. Fixed the issue: The identification of LBS middle north latitude and west longitude is incorrect.
4. Fixed the issue: Some GNSS stress test scenarios, accidental crash problems.
5. Optimized the "AT+CPOF" URC.

Version: 2374B04_SIM767XM5A_M

[New Features]

1. New command: "AT+CPOF=1" Fast shutdown.

[Improved Features]

1. Fixed the issue: "AT+COPS" No return operator information in some areas.

Version: 2374B03_SIM767XM5A_M

[New Features]

[Improved Features]

1. Fixed the issue: Some customers return error when accessing certain urls (updated the configuration of MBEDTLS).
2. Fixed the issue: WEBSOCKET HTTP stress test scenarios, accidental crash problems.
3. Optimized the RF ACLR.
4. Other general questions.

Version: 2374B02_SIM767XM5A_M

[New Features]

1. The gateway IP address of the module is changed from 192.168.10.1 to 192.168.0.1

[Improved Features]

1. Fixed the issue: Modified hibernation mode, PSM exception problem.
2. Fixed the issue: Do not connect USB open GPS to obtain NMEA data, the module crashes.
3. Other general questions.

Version: 2374B01_SIM767XM5A_M

[New Features]

1. The PATCH related to the platform baseline has been imported and upgraded 71 to baseline 74.

2. "AT+CTBURST" supports RX testing.
3. Added "AT+SIGNALS".
4. "AT+CGNSSAGPS" was renamed to "AT+CAGPS".
5. "AT+IFC" changes "Parameter Saving Mode" to "NO_SAVE".

[Improved Features]

1. Fixed the issue: CSMP will change when hard reboot (QCX216-1604).
2. Fixed the issue: The TCP/MQTT connection is abnormal, such as the MQTT payload cannot be received when the payload exceeds 384 bytes.
3. Fixed the issue: The user name and password parameters of the AT+CGAUTH command are in an abnormal order and do not match the document.
4. Optimized the return error or display error of some instructions.

SIMCom
Confidential