


EHS Procedure QuickCard

FC-GL-EHS-SAF-0707: Electrical Safety



- Electrical Work Practices
- Energized Electrical Work Permit
- **Work with/on/around Capacitors**
- Arc and Shock Assessment Tool
 - PPE requirements
 - Approach Boundary Determination



Key Changes

- Introduction of Arc Blast Hazard
- FC-GL-EHS-SAF-0707-G3 Working on/with/around Capacitors
- 600V Threshold changed to 1000V



Key Tools

- FC-GL-EHS-SAF-0707-F1: Energized Electrical Work Permit
- FC-GL-EHS-SAF-0707-G1: Arc & Shock Assessment Guidance
- **FC-GL-EHS-SAF-0707-G3: Work on/with/around Capacitors**
- NFPA 70E Standard for Electrical Safety in the Workplace 2021 edition* - Tables available through GE Standards Library:
<https://edms1.pw.ge.com/trslibrary/>



Further Work / Support

- FC-GL-EHS-SAF-0703: Lockout Tagout
- CRSE GE-EHS-280: Electrical Safety Advanced
- **Full Implementation by: March 1st, 2023 – note all requirements in effect immediately**

*NOTE: Due to copyright protections NFPA 70E including tables cannot be reproduced in the procedure – all tables are available free of charge through the GE Standards Library