

M301 Cooling System Inspection

Purpose:

Provide a standard procedure for inspecting the cooling system of M301 when abnormal temperature is detected.

Applicable Machine:

M301 – CNC Machine

Trigger conditions:

- High-temperature warning
- Abnormal temperature increase
- Reduced cooling performance
- Repeated temperature alarms

Safety precautions:

1. Stop the machine according to the approved shutdown procedure.
2. Isolate power before physical inspection.
3. Allow hot components to cool before inspection.
4. Wear required PPE.
5. Do not bypass temperature or safety sensors.

Inspection procedure:

1. Check the coolant level.
2. Check coolant flow.
3. Inspect the cooling lines for blockage or leakage.
4. Inspect the cooling filter.
5. Check the cooling unit/fan.
6. Check the temperature sensor.
7. Record the observed temperature and condition.
8. Escalate to maintenance if the abnormal condition persists.

Possible findings:

- Low coolant level
- Blocked filter
- Restricted coolant flow

- Cooling-system malfunction
- Sensor abnormality

Required action:

If overheating continues after basic inspection, stop operation and request maintenance inspection