

CNC Machine Troubleshooting

Purpose:

Provide general troubleshooting guidance for CNC machine abnormalities.

Applicable Machines:

M101, M201, M301, M401 and equivalent CNC machines.

Common symptoms:

- Overheating
- Unexpected shutdown
- Abnormal vibration
- Unusual noise
- Reduced production output
- Repeated alarms

Initial checks:

1. Identify the machine alarm.
2. Record the time and operating shift.
3. Check the machine status.
4. Check relevant operating parameters.
5. Check whether the problem has occurred previously.
6. Refer to the appropriate machine-specific SOP.
7. Escalate unresolved issues to maintenance.

Documentation requirement:

Every significant machine abnormality should be recorded with the machine ID, date, time, symptom, and action taken.