STM32F105RBT6(Tybe-B)开发板原理图

修订说明:

201812,V1.0,初次完成;

201901,V1.1,修改了 SOT-323 封装错误;

201903,V2.0,修改板内 5V 供电芯片为 MP2451;

















