

East Bay Diagnostics

Berkeley, CA

DIAGNOSTIC REPORT

DR-260919-08

2026-09-19

Vehicle	2015 Mazda CX-5	Mileage	112,330
Customer concern	Check engine light on.	Record type	Diagnostic Report

Technician findings

- Stored EVAP small-leak fault code.
- Smoke test revealed loose fuel-cap seal; no other visible leak found.

Status	Work performed	Parts	Labor	Line total
Completed	Performed computer scan and diagnostic testing	-	1.0h x \$170.00 = \$170.00	\$170.00
Completed	Performed EVAP smoke test	\$15.00	0.8h x \$170.00 = \$136.00	\$151.00
Completed	Replaced fuel cap	\$42.00	-	\$42.00

Parts subtotal	\$57.00
Labor subtotal	\$306.00
Subtotal	\$363.00
Sales tax	\$5.84
Total	\$368.84

Recommendations

- If the warning light returns, schedule follow-up diagnosis.

Warranty: Not listed

Notes: Fault codes cleared after repair; readiness monitors require normal drive cycles.