

Bay Tire House

San Bruno, CA

SERVICE RECORD

SR-260919-14

2026-09-19

Vehicle	2020 Tesla Model 3	Mileage	48,600
Customer concern	Replace rear tires and check alignment.	Record type	Service Record

Technician findings

- Rear tires at replacement threshold.
- Front tread depth measured 5/32 in.

Status	Work performed	Parts	Labor	Line total
Completed	Installed two rear 235/45R18 tires	\$590.00	-	\$590.00
Completed	Mounted and balanced two tires	-	0.7h x \$145.00 = \$101.50	\$101.50
Completed	Performed four-wheel alignment	-	1.0h x \$145.00 = \$145.00	\$145.00

Parts subtotal	\$590.00
Labor subtotal	\$246.50
Fees	\$10.00
Subtotal	\$846.50
Sales tax	\$54.58
Total	\$901.08

Recommendations

- Rotate tires per vehicle manufacturer guidance where applicable.

Warranty: Tire manufacturer warranty applies.

Notes: Alignment measurements within specification after adjustment.