

Twin Peaks Automotive

San Francisco, CA

SERVICE RECORD

SR-260919-18

2026-09-19

Vehicle	2017 Audi A4	Mileage	90,540
Customer concern	Rough idle and intermittent EPC warning.	Record type	Service Record

Technician findings

- Misfire detected on cylinder 2.
- Ignition coil output inconsistent during swap test.

Status	Work performed	Parts	Labor	Line total
Completed	Performed engine performance diagnostic	-	1.2h x \$195.00 = \$234.00	\$234.00
Completed	Replaced ignition coil - cylinder 2	\$92.00	0.4h x \$195.00 = \$78.00	\$170.00
Completed	Replaced spark plug set	\$88.00	1.0h x \$195.00 = \$195.00	\$283.00

Parts subtotal	\$180.00
Labor subtotal	\$507.00
Fees	\$15.00
Subtotal	\$702.00
Sales tax	\$15.52
Total	\$717.52

Recommendations

- Return if warning message or rough idle returns.

Warranty: 12 months / 12,000 miles on listed ignition repair.

Notes: Idle quality normal after repair.