

North Beach Auto Works

San Francisco, CA

SERVICE RECORD

SR-260919-21

2026-09-19

Vehicle	2016 Acura TLX	Mileage	105,700
Customer concern	Front brake noise; additional rotor wear found after disassembly.	Record type	Service Record

Technician findings

- Front pads worn below service limit.
- Rotor thickness below shop replacement threshold after measurement.

Status	Work performed	Parts	Labor	Line total
Completed	Replaced front brake pads - originally authorized	\$185.00	1.2h x \$160.00 = \$192.00	\$377.00
Completed After Additional Authorization	Replaced front brake rotors - added after customer authorization	\$295.00	0.5h x \$160.00 = \$80.00	\$375.00

Parts subtotal	\$480.00
Labor subtotal	\$272.00
Fees	\$18.00
Subtotal	\$770.00
Sales tax	\$41.40
Total	\$811.40

Recommendations

- Recheck front brake wear at next scheduled inspection.

Warranty: 12 months / 12,000 miles.

Notes: Additional rotor replacement authorized by customer before work was completed.