

Mission EV Service

San Francisco, CA

EV SERVICE RECORD

EV-SR-260919-26

2026-09-19

Vehicle	2022 Hyundai IONIQ 5 Powertrain: Battery Electric	Mileage	43,880
Customer concern	AC charging intermittently stops shortly after connection.	Record type	Service Record

Technician findings

- Charge inlet lock actuator intermittently failed to engage during repeated AC charging tests.

Status	Work performed	Parts	Labor	Line total
Completed	Performed EV charging-system diagnostic	-	1.0h x \$185.00 = \$185.00	\$185.00
Completed	Inspected charge inlet and connector	-	0.5h x \$185.00 = \$92.50	\$92.50
Completed	Replaced charge-port lock actuator	\$285.00	1.1h x \$185.00 = \$203.50	\$488.50

Parts subtotal	\$285.00
Labor subtotal	\$481.00
Fees	\$12.00
Subtotal	\$778.00
Sales tax	\$24.58
Total	\$802.58

Recommendations

- Monitor AC charging behavior and return if charging interruptions recur.

Warranty: 12 months / 12,000 miles on listed repair.

Notes: AC charging verified after repair.

EV safety note: This record summarizes completed professional service. It is not a DIY guide for high-voltage systems.