Soldering Workshop

Clint Grimsley clint.grimsley@gmail.com

HackRVA

August 13, 2012

Outline

- Physics
 - Heat
 - Gravity



Heat

Physics is how to make oneself comfortable handling a 750°F iron and slinging molten lead around

- Heat the work, not the solder
- Too much Rosin is your mortal enemy

Gravity

 Understand the best way to mount your work, so your project doesn't crash to the floor and your components don't fall all over the place