

NORD SOFTWARE LIBRARY DISKETTE

Containing : TEST PROGRAMS NO. 1 FOR NORD-10,
NORD-12 AND ND-100

Directory Name : ND-10324F
User : FLOPPY-USER

File access:						
Num	File name	Type	Public	Friend	Own	Pages Bytes
0	BIG-RAND-1876C	BPUN	R	RWA	RWACD	3 4662
1	CONFI-INV-1672N	BPUN	R	RWA	RWACD	17 34100
2	DIMS-1453F	BPUN	R	RWA	RWACD	9 17004
3	DISC-TEMA-E	BPUN	R	RWA	RWACD	24 48366
4	EXTEN-ONE-1519B	BPUN	R	RWA	RWACD	3 4768
5	FLOPP-FORM-1990B	BPUN	R	RWA	RWACD	3 5754
6	FLOPPY-RAN-1988B	BPUN	R	RWA	RWACD	5 9526
7	HDLC-MEGALINK-B	BPUN	R	RWA	RWACD	14 28350
8	LP-TEST-1878C	BPUN	R	RWA	RWACD	9 18392
9	MEMORY-C	BPUN	R	RWA	RWACD	18 35872
10	MOVER-1863C	BPUN	R	RWA	RWACD	2 3572
11	MULTI-1820P	BPUN	R	RWA	RWACD	12 22908
12	SUPER-RAND-2222C	BPUN	R	RWA	RWACD	6 12210
13	TANB-MAG-1559H	BPUN	R	RWA	RWACD	5 8484
14	TERMINAL-ASYNC-C	BPUN	R	RWA	RWACD	15 29756

Total: 15 files using 145 pages

16 FEB 1983

PRODUCT	NAME	ND-NUMBER	CATEGORY
	TEST-PROGRAMS No. 1 for ND-10, ND-12 and ND-100.	10324F	T
		ND-NUMBER FOR SOURCE	10327F
ISSUED	DATE: 1 FEB 1983	BY (INITIALS)	TLS
COMPUTERS	X 10 ! X 12 ! 50 ! X 100!	500!	
INSTR.SET	48 BIT FL. ! 32 BIT FL. !	COMMERCIAL!	
OP.SYSTEM	SIN III VS! SIN III RT!	X ALONE	
DOCUMEN-TATION	NUMBER: ND-30.005.2 TITLE: Testprogram description.		
PURPOSE	Testprograms for CPU, memory, discs and peripherals.		
PROGRAMS (FILES)	PROG.NUMB NAME TYPE CONTAINING		
	HAR-1876C BIG-RAND BPUN Random test for big disc		
	HUT-1672N CONFI-INV BPUN Checks configuration		
	HUT-1453F DIMS BPUN Utility program 10MB disc		
	203134E DISC-TEMA BPUN Utility program discs		
	HAR-1519B EXTEN-ONE BPUN Instruction check		
	HUT-1990B FLOPP-FORM BPUN Discette formatting		
	HAR-1988B FLOPPY-RAN BPUN Random test floppy-disc.		
	203447B HDLC-MEGALINK BPUN HDLC and MEGALINK testprog		
	HAR-1878C LP-TEST BPUN Line printer testprogram		
	203396C MEMORY BPUN Memory test program		
	HAR-1863C MOVER BPUN Memory testprogram		
	HAR-1820P MULTI BPUN Memory test program		
	HAR-2222C SUPER-RAND BPUN Random test for discs		
	HAR-1559H TANB-MAG BPUN Tandberg tape testprogram		
	203198C TERMINAL-ASYNC BPUN Terminal testprogram		

Place floppy in FLoppy Disc Controller 1, Unit 0.
Press Master Clear, Type 1560& and LOAD <program>.

PRODUCT	NAME	ND-NUMBER
	TEST-PROGRAMS No. 1 for ND-10, ND-12 and ND-100.	10324F

BIG-RAND Date: 78.05.30 (TLS) Boundaries: 0<4000
Start address: 0 Restart address: 20

The test can only be run on Disc System 1. Unit numbers are given as a sequence of numbers (0-7) separated by space, terminated by CR.

Status appears as two words. The first word is the hardware status reg. The upper four bits in the second word have the following meaning:

Bit 12: Seek error.
Bit 13: Core Address Reg. not as expected.
Bit 14: Block Address out of range.
Bit 15: Illegal device operation code.

Bit 12-15 all ones: Controller not active after activate.

CONFI-INV Date: 82.09.01 (TAE) Boundaries: 0<40577
Start address: 0 Restart address: 20

Includes the TEST-MONITOR-2441F and MON-LIBR-2442F

7IMS Date: 81.02.01 (TLS) Boundaries: 0<20033
Start address: 0 Restart address: 20

Includes the TEST-MONITOR-2441C.

DISC-TEMA Date: 83.02.01 (TLS) Boundaries: 0<56534
Start address: 0 Restart address: 20

Includes the TEST-MONITOR-2441G and MON-LIBR-2442G.

EXTEN-ONE Date: 77.09.15 (TAE) Boundaries: 0<4065
Start address: 20 Restart address: 20

Runs ONE-CHECK on levels 1-15.

Location 0432 contains SAT 1 (171001)

NORSK DATA A/S		NORD SOFTWARE LIBRARY	PAGE 3 OF 4
PRODUCT	NAME	ND-NUMBER	
	TEST-PROGRAMS No. 1	10324F	
	for ND-10, ND-12 and ND-100.		

Is wanted on the Punch, change to 171003.
 Is wanted on the Line-Printer, " 171005.
 Is wanted on the Terminal 2, " 171007.

FLOPP-FORM Date: 82.01.15 (SUP) Boundaries: 0<5042
 Start address: 20 Restart address: 20

FLOPPY-RAN Date: 82.01.15 (SUP) Boundaries: 0<10600
 Start address: 0 Restart address: 20

HDLC-MEGALINK Date: 83.02.01 (SUP) Boundaries: 0<33104
 Start address: 0 Restart address: 20

Includes the TEST-MONITOR-2441G and MON-LIBR-2442G.

LP-TEST Date: 82.01.15 (SUP) Boundaries: 0<21322
 Start address: 0 Restart address: 20

Includes the TEST-MONITOR-2441E.

MEMORY Date: 83.02.01 (TAE) Boundaries: 0<42365
 Start address: 0 Restart address: 20

Includes the TEST-MONITOR-1441G and MON-LIBR-2442G.

MOVER Date: 77.04.29 (TAE) Boundaries: 0<2737
 Start address: 400 Restart address: None

Self-documenting.

MULTI Date: 82.09.01 (TAE) Boundaries: 0<25643
 Start address: 0 Restart address: 20

Includes the TEST-MONITOR-2441E and MON-LIBR-2442E

MULTI may be used to test memory on ND-10 and ND-100.
 MULTI reads from DMA-devices in test mode.

NORSK DATA A/S		NORD SOFTWARE LIBRARY	PAGE 4 OF 4
PRODUCT	NAME	ND-NUMBER	
	TEST-PROGRAMS No. 1	10324F	
	for ND-10, ND-12 and ND-100.		

It should not be necessary to turn off the disc/drum, but it may be the best.

SUPER-RAND Date: 79.11.30 (TLS) Boundaries: 0<13276
 Start address: 20 Restart address: 20

Qualitive read/write/seek test for disc and controller.

TANB-MAG Date: 83.02.01 (TLS) Boundaries: 0<7577
 Start address: 20 Restart address: 20

TERMINAL-ASYNC Date: 83.02.01 (SUP) Boundaries: 0<34403
 Start address: 0 Restart address: 20

Includes the TEST-MONITOR-2441G and MONITOR-LIBRARY-2442G.

NORSK DATA A/S		NORD SOFTWARE LIBRARY	PAGE 1 OF 1
		REVISION LOG	
PRODUCT	NAME	ND-NUMBER	
	DISC-TEMA	10324F	
ISSUED	DATE 83.02.01	BY (INITIALS) DG	
REASON	* ERROR CORRECTION	DIFFERENT ENVIRONMENT	
	CHANGE/ADDITION	NEW PROGRAM	
FILES	PROG.NUMB. NAME		
CHANGED	203134E DISC-TEMA		
OR NEW			
FILES			

The E-version of DISC-TEMA includes the G-versions of the TEST-PROGRAM-MONITOR and the MONITOR-LIBRARY.

The following error have been reported in DISC-TEMA-D:

- i) **Formatting with track-allocation:**
On other units than 0 formatting with track-allocation does not work unless unit 0 is ready.
- ii) **Running DISC-TEMA via modem:**
It is impossible to run any test program which includes the F-version of the monitor and library, via modem.
- iii) **Too small amount on artificially divided disc with spare track:**
When using artificially divided discs (2-75Mb or 3-75Mb) which has reallocated tracks, the amount is set too small. This has the effect that fx. copy does not include the last pages of the directory. The number of pages not included are 90 on 2-75Mb and 171 on 3-75Mb.
- iv) **Introducing "Data error" on disc by pressing "ESC":**
If "ESC" is pressed during a write operation the sector beeing written will not be correctly written. The sector will therefor contain a "Data error".

In the E version of DISC-TEMA, all the mentioned errors are corrected.

NORSK DATA A/S		NORD SOFTWARE LIBRARY REVISION LOG		PAGE 1 OF 1
PRODUCT	NAME HDLC-MEGALINK			ND-NUMBER 10324F
ISSUED	DATE 83.02.01		BY (INITIALS) SUP	
REASON	* ERROR CORRECTION CHANGE/ADDITION		DIFFERENT ENVIRONMENT NEW PROGRAM	
FILES CHANGED OR NEW FILES	PROG.NUMB. NAME 203447B HDLC-MEGALINK			

The following errors have been reported in HDLC-MEGALINK-A

- i) When a Memory Parity or Memory Out of Range Error occurs, the PES and PEA given in the error message are not necessary correct.
- ii) When the program started it was not able to detect more than 14 HDLC's, it is now capable of detecting up to 32 HDLC/MEGALINKS.

These errors have been corrected in the HDLC-MEGALINK-B version. The program now includes the G-version of TEST-MONITOR and LIBRARY.

NORSK DATA A/S		NORD SOFTWARE LIBRARY	PAGE 1 OF 1
		REVISION LOG	
PRODUCT	NAME	ND-NUMBER	
	MEMORY	10324F	
ISSUED	DATE 1 FEB 1983	BY (INITIALS) TAE	
REASON	* ERROR CORRECTION	DIFFERENT ENVIRONMENT	
	* CHANGE/ADDITION	NEW PROGRAM	
FILES	PROG.NUMB. NAME		
CHANGED	203396C MEMORY		
OR NEW			
FILES			

ERRORS CORRECTED:

- * An error in the TEST-BUSC-DATAWAY subcommand has been corrected. This error caused a wrong BUSC number to be typed during error-printouts.
- * A minor bug in the DEFINE-TEST-AREA command concerning default parameters has been corrected.

NORSK DATA A/S		NORD SOFTWARE LIBRARY	PAGE 1 OF 1
		REVISION LOG	
PRODUCT	NAME	ND-NUMBER	
	TANB-MAG-1559	10324F	
ISSUED	DATE 83.02.01	BY (INITIALS) DG	
REASON	* ERROR CORRECTION	DIFFERENT ENVIRONMENT	
	CHANGE/ADDITION	NEW PROGRAM	
FILES	PROG.NUMB. NAME		
CHANGED	1559H TANB-MAG		
OR NEW			
FILES			

The following error has been reported in TANB-MAG-1559G:

i) **Unmotivated error message:**

The program does not wait long enough for the transfer to finish. This results in the error message:
MAG. TAPE NEVER READY
Being printed unmotivated.

In the TANB-MAG-1559H version, the mentioned error is corrected.

PRODUCT	NAME TERMINAL-ASYNC	ND-NUMBER 10324F
ISSUED	DATE 83.02.01	BY (INITIALS) SUP
REASON	* ERROR CORRECTION * CHANGE/ADDITION	DIFFERENT ENVIRONMENT NEW PROGRAM
FILES CHANGED OR NEW FILES	PROG.NUMB. NAME 203198C TERMINAL-ASYNC	

The following error has been reported in TERMINAL-ASYNC-B
IOX ERROR during INTERFACE-TEST.

Due to some error in program, it sometimes tries to read IDENT
while it is impossible and an IOX error- message appears.

This error has been corrected in the TERMINAL-ASYNC-C version.

There has been one change in the INTERFACE-TEST

It is now possible to run this test not in maintenance mode. To do
that an external connection (dummy plug etc.) is required between the
input and output channel on the devices that are to be tested.

In the error messages, it is added what the speed was when the error
occured.

The program now includes the G-version of TEST-MONITOR and LIBRARY.