



PC WORX	Phoenix Contact GmbH & Co. KG Flachsmarktstraße 8 32825 Blomberg Germany	Sheet number 1	
Current POU: Main:Main	lab1	This copy printed out at: 12.05.2025 22:27:51	

Name	Туре	Usage	Description	Init	letai P[ОФРО	TB	Hidden	ue as H	fault Hidden-	Vahdant V	alotOnPl	Device	Signal	Alias
Default															
Sensor_1	BOOL	VAR_EXTE													
Washing	BOOL	VAR_EXTE													
TON_1	TON	VAR													
Timer1	BOOL	VAR													
TON_2	TON	VAR													
Timer2	BOOL	VAR													
Detergent	BOOL	VAR_EXTE													
TON_3	TON	VAR													
Timer3	BOOL	VAR													
Motor_Forward	BOOL	VAR_EXTE													
Sensor_3	BOOL	VAR_EXTE													
Motor_Backward	BOOL	VAR_EXTE													
Sensor_4	BOOL	VAR_EXTE													
Steaming	BOOL	VAR_EXTE													
Drying	BOOL	VAR_EXTE													
TON_4	TON	VAR													
Timer4	BOOL	VAR													
Drying_Motor	BOOL	VAR_EXTE													
TON_5	TON	VAR													
Timer5	BOOL	VAR											•		
Ready	BOOL	VAR_EXTE													
Sensor_2	BOOL	VAR_EXTE													
RS 1	RS	VAR													

PC WORX	Phoenix Contact GmbH & Co. KG Flachsmarktstraße 8 32825 Blomberg Germany	Sheet number 1		
Current POU: MainV:Main	lab1	This copy printed out at: 12.05.2025 22:28:04		