
3D Viewer
File Edit View Preferences Help
Copper Keepouts shown on Dwgs layer
U1
R1
D1
BZ1
SWCLK
SWDIO
Appearance
Board Body
F.Cu
B.Cu
Adhesive
Solder Paste
F.Silkscreen
B.Silkscreen
F.Mask
B.Mask
User.Drawings
User.Comments
User.Eco1
User.Eco2
Through-hole Mode
SMD Models
Virtual Models
Values
References
Footprint Text
Off-board Silkscreen
3D Axis
Background Start
Background End
Presets (Ctrl+Tab):
Viewports (Shift+Tab):


*raspberry pico — PCB Editor
File Edit View Place Route Inspect Tools Preferences Help
Design Rules Checker
Refill all zones before performing DRC
Test for parity between PCB and schematic
Report all errors for each track
Violations (0) Unconnected Items (0) Schematic Parity (not run) Ignored Tests (4)
Show: All Errors 0 Warnings 0 Exclusions
Save...
Delete Marker
Delete All Markers
Run DRC
Close
Zoom 1.50
Appearance
Layers Objects Nets
B.Adhesive
F.Paste
B.Paste
F.Silkscreen
B.Silkscreen
F.Mask
B.Mask
User.Drawings
User.Comments
User.Eco1
User.Eco2
Edge.Cuts
Margin
Layer Display Options
Presets (Ctrl+Tab):
All Layers
Viewports (Shift+Tab):
Selection Filter
All items
Locked items
Footprints
Text
Tracks
Vias
Pads
Graphics
Zones
Rule Areas
Dimensions
Other items
Pads 99
Vias 0
Track Segments 36
Nets 44
Unrouted 0
File 'C:\Users\Admin\Documents\t...
Z 1.45
X 216.5000 Y 99.0000
dx 216.5000 dy 99.0000 dist 238.0614
grid 0.5000
mm
Select item(s)