

**DHC-8-402****MINIMUM EQUIPMENT LIST*****ENGINES INDICATING******ATA 77*****77-30-1 Engine Monitoring Unit (EMU)**

Interval	Installed	Required	Procedure
D	1	0	NIL

May be inoperative provided alternate procedures are established and used to record engine data.

Minimum Equipment List Procedures (MELP)**Placard**

Inoperative Engine Monitoring Unit (EMU) must be placarded in the flight compartment.

Operating Procedures

None required.

Maintenance Procedures

1. Placard the inoperative EMU.
2. Required Engine Parameters for stabilized cruise will be noted from Tech Log Page and sent to monitoring agency for cater for the absence of downloaded data.
3. Make appropriate entry in the aircraft journey log.

■ ■ ■ ■

ISS III R00**APPROVED BY DAW DELHI, DATED -**

Signature valid

Signed by: Manoj
Kumar Bajpai
Director
(Airworthiness)
Date: 07-Jun-
2024 13:52:49

77-30-1. 1

**DHC-8-402****MINIMUM EQUIPMENT LIST*****ANNEXURE B*****Time Limited Dispatch****Scenario-1 With the Engine Monitoring Unit (EMU) Serviceable**

1 The EMU records the date and time of events so it is possible to know precisely when a particular fault code occurred.

2 Time counting for LTD (Long Term Dispatch) or STD shall be started at the moment the fault code occurred and rectification of the fault code can be scheduled accordingly.

3 Example:**NOTE: AMP mandates check for FADEC Faults at every 50 Hrs**

a A fault code is logged 30 flight hours after the last check for fault codes. Therefore, the fault has been present for 20 hours before being discovered.

b If the fault is STD, then there will be (150-20) 130 hours left to rectify it.

c If the fault is LTD, then there will be (500-20) 480 hours to left rectify it.

Scenario-2 Without the EMU

1 In this scenario, it is not known precisely when a particular fault code occurred.

2 It must be assumed that the fault occurred immediately following the last check for fault codes.

3 Example:**NOTE: AMP mandates check for FADEC Faults at every 50 Hrs**

a A fault code is found. The fault is assumed to have been present for 50 hours before being discovered.

b If the fault is STD, then there will be (150-50) 100 hours left to rectify it.

c If the fault is LTD, then there will be (500-50) 450 hours to rectify it.

Levels of TLD

There are four levels of TLD. These are:

a) Fully operational system:

A system is considered fully operational when no faults are annunciated

b) Long Term Dispatch

The control system is on a long term dispatch if the sum of the TLD risk associated with the annunciated faults is between 10 and 74.9.

c) Short Term Dispatch

The control system is on a short term dispatch, if the sum of the TLD risk associated with the annunciated faults is equal to 75 or more.

ISS III R00**APPROVED BY DA****Signature valid**

Signed by: Manoj
Kumar Bajpai
Director
(Airworthiness)
Date: 07-Jun-
2024 13:52:49

Ann B 1

**DHC-8-402****MINIMUM EQUIPMENT LIST*****ANNEXURE B*****d) No Dispatch**

FADEC will cause the POWERPLANT caption to come into view on the Engine Display. This message means that no more flights are allowed until at least some of the TLD faults present are corrected.

For multiple messages associated TLD risk factors are to be summed up obtain total risk factor. The TLD risk factors are tabulated below:

Time Limited Dispatch Faults and Risk Factors

Fault Codes	Description	TLD Risk
700	A/D Test Latched Failed (EEC Internal Fault)	32.3
708	EEPROM Read/Write Fault Latch Flag (EEC Internal Fault)	76.0
709	High Level Analog Signals Drift Latched Failed (EEC Internal Fault)	16.7
710	Low Level Analog Signals Latched Failed (EEC Internal Fault)	16.7
711	FADEC Cross-link Latched Failed (EEC Internal Fault)	76.0
716	NH Speed Sensing Intermittent Fault	16.2
717	NL Speed Sensing Intermittent Fault	10.0
718	NP Speed Sensing Intermittent Fault	16.2
719	Torque Sensing Intermittent Fault	16.2
720	Inlet Temp (T1.5) Sensing Intermittent Fault	16.6
723	PAMB Sensor Input Signal Intermittent Fault (EEC Internal Fault)	14.5
724	P3 Sensor Input Signal Intermittent Fault	10.0
725	P2.2 BOV Input Signal Intermittent Fault	22.7
726	PLA Input Signal Intermittent Fault	21.0
727	WF Sensor Input Signal Intermittent Fault	19.2
732	NH Speed Sensing Latched Failed	16.2
733	NL Speed Sensing Latched Failed	10.0
734	NPT Speed Sensing Latched Failed	16.2
735	Torque Shaft Deflection Sensing Latched Failed	16.2
736	Inlet Temp (T1.8) Sensor Input Latched Failed	16.6
739	PAMB Sensor Input Latched Failed (EEC Internal Fault)	14.5
740	P3 Sensor Input Latched Failed	10.0
741	P2.2 HBOV LVDT Input Latched Failed	22.7
742	PLA RVDT Input Latched Failed	21.0
743	FMU Metering Valve LVDT Latched Failed	19.2
759	AC Circuit Drift Correction Latched Failed (EEC Internal Fault)	29.7
760	AC Circuit Gain Correction Latched Failed (EEC Internal Fault)	29.7
776	P2.7 BOV Torque Motor Wraparound Latched Failed (EEC Internal Fault)	10.0
778	P2.2 BOV Crosscheck Latched Failed	29.7
779	P2.2 BOV Torque Motor Wraparound Latched Failed (EEC Internal Fault)	10.0
782	NH Crosscheck Latched Failed	16.2

ISS III R00**APPROVED BY DA  Signature valid**

Signed by: Manoj
Kumar Bajpai
Director
(Airworthiness)
Date: 07-Jun-
2024 13:52:49

Ann B 2



DHC-8-402

MINIMUM EQUIPMENT LIST

ANNEXURE B

783	NL Crosscheck Latched Failed	10.0
784	NPT Crosscheck Annunciation Fail Flag	16.2
785	Overspeed Open Coil/LSS Short Latched Failed: Bit 6 of OPCLSSIND	10.0
786	Overspeed NH Below Idle Detect Latched Failed: Bit 6 of OSBIDIND	10.0
787	Overspeed High-side Overcurrent Latched Failed	10.0
788	P3 Drift Correction Latched Failed	10.0
789	P3 Excitation Circuit W/A Latched Failed	10.0
790	P3 Crosscheck Latched Failed	10.0
791	PAMB Drift Correction Circuit Latched Failed (EEC Internal Fault)	17.1
792	PAMB Crosscheck Annunciation Fail Flag (EEC Internal Fault)	17.1
793	PAMB Excitation Circuit W/A Latched Failed (EEC Internal Fault)	17.1
799	PLA Crosscheck Latched Failed	21.3
803	T1.5 Crosscheck Latched Failed	16.8
806	PAMB Temperature RTD Compensation Circuit Latched Failed (EEC Internal Fault)	17.1
810	WFMV Crosscheck Latched Failed	29.7
811	WF Torque Motor Wraparound Latched Failed (EEC Internal Fault)	10.0
815	Torque Motor Rail Input Latched Failed (EEC Internal Fault)	22.7
825	Torque Motor Command Null Wraparound Fault Indication	22.7
900	Permanent Magnet Alternator Voltage Failure	76.0
908	HP Wraparound Latched Failed (EEC Internal Fault)	10.0
912	P2.2 HBOV Valve Position Track Check Latched Failed	22.7
913	P2.2 HBOV Valve Wraparound Latched Failed	22.7
919	NH Probe Failed Open Circuit	16.2
921	NL Probe Failed Open Circuit	10.0
922	NPT/Q Probe Failed Open Circuit	16.2
923	Overspeed Solenoid Low-side Switch Failure	10.0
924	Overspeed Solenoid Open High-side Switch Failure	10.0
925	Overspeed Solenoid Shorted High-side Failure	10.0
928	P3 Sensor Reasonability Check Failure	10.0
934	Normal Engine Shutdown Failed	Note
935	WF Metering Valve Position Track Check Latched Failed	29.7
936	WF Wraparound Latched Failed	22.8
954	Minimum Pressure Shut-off Valve Seal Leak Maintenance Flag	Note
967	Torque Motor Rail Over current Confirmed Fault	22.7
976	Metering Valve Failed During Shutdown	Note
977	Channel to Channel Switchover Failed (EEC Internal Fault)	76.0
978	Pilot De-power Extended Period Fault (EEC Internal Fault)	22.7

NOTE:

The fault codes 934, 954 and 976 will cause the POWERPLANT caption to come into view on the Engine Display. These faults are related to a non-redundant fuel shut-off function. It is possible that they can prevent you from doing a fast engine shutdown.

ISS III R00

APPROVED BY DA  **Signature valid –**

Signed by: Manoj
Kumar Bajpai
Director
(Airworthiness)
Date: 07-Jun-
2024 13:52:49

Ann B 3

**DHC-8-402****MINIMUM EQUIPMENT LIST*****ANNEXURE C*****AIRCRAFT DETAILS**

SN	MODEL	REGISTRATION	MSN
1	DHC-8-402	VT-SUY	4339
2	DHC-8-402	VT-SUV	4340
3	DHC-8-402	VT-SUS	4346
4	DHC-8-402	VT-SUR	4342
5	DHC-8-402	VT-SUQ	4406
6	DHC-8-402	VT-SUP	4412
7	DHC-8-402	VT-SUO	4404
8	DHC-8-402	VT-SUM	4402
9	DHC-8-402	VT-SUL	4400
10	DHC-8-402	VT-SUK	4398
11	DHC-8-402	VT-SUJ	4396
12	DHC-8-402	VT-SUI	4395
13	DHC-8-402	VT-SUH	4389
14	DHC-8-402	VT-SUG	4387
15	DHC-8-402	VT-SUF	4382
16	DHC-8-402	VT-SUE	4379
17	DHC-8-402	VT-SUD	4378
18	DHC-8-402	VT-SUB	4374
19	DHC-8-402	VT-SQE	4591
20	DHC-8-402	VT-SQD	4589
21	DHC-8-402	VT-SQC	4586
22	DHC-8-402	VT-SQB	4584
23	DHC-8-402	VT-SQA	4583
24	DHC-8-402	VT-SJU	4336

ISS III R06

APPROVED BY DAW DELHI, DATED-

ANN C.01

Signature valid



Signed by: Manoj
Kumar Bajpai
Director
(Airworthiness)
Date: 07-Jun-
2024 13:52:49