

Electrical Circuits for Engineers (EC1000)




Lecture-12 Electrical Machines

12/2/2023 Electrical Machines 1



Types of Electrical Machines


Electrical Machines are Electro Mechanical Energy Conversion devices, which converters Electrical energy into mechanical energy and vice-versa






How they work??

Two electromagnetic conversion phenomena:



- Induced voltage: when a conductor moves in a magnetic field, voltage is induced in the conductor. (Generator action)
- Force and developed torque: when a current-carrying conductor is placed in a magnetic field, the conductor experiences a mechanical force. (Motor action)






Rotating Electrical Machines


Fixed stator: This (normally) sets up magnetic field.

Rotating rotor: This (normally) carries currents (either

supplied from a power source or (induced).



Stator sets up B field



Current (I) flows in rotor.


Force on conductor: F=IB*l*

Torque: T=F*r*





Rotor rotates (anticlockwise) 1/4 revolution later we have





For a particular machine:

- How B is produced?
- How do we get currents in rotor to produce continuous torque?




Principle of Operation of DC Motors






Field winding (2 coils in series as shown) carries field current I_f

 I_f sets up magnetic field shape as shown





Rotor carries "armature" winding. Armature current i_a fed to through commutator and brushes.

This feeds i_a to different windings as rotor rotates. Result is that the current distribution *in space* is fixed.


Force = $i_a B_i l$ always in direction shown since current distribution is fixed in space.

Torque = Force x radius

Torque = i_a B.l r




Permanent Magnet DC Motor









1. Force on conductor carrying I in field B



$$F = I B l$$
 $l = length of$
conductor in field




2. Voltage (emf) induced in conductor traveling in field B



$$e = vB l$$


 $e = voltage induced$
along length l






EMF induced in DC- Motor

- e induced in each conductor
- N conductors are all in series
- Therefore total "back-emf" induced in armature winding is E = Ne
- $E = N \nu B l$ $\nu = \omega r (\omega = angular velocity, rad/s)$ $E = N\omega r B l = k\omega$



• E is proportional to ω

Equivalent circuit of a separately excited DC motor







Cross section of a permanent magnet DC motor

Direction of B

Winding Axis of
Rotor

Note it is perpendicular to the magnet flux





Rotor with Commutator and End Frame with Brushes of Simple Permanent Magnet Machine




Characteristics of DC Machine


- I_f sets field B. This normally constant
- Torque = $k i_f i_a$. If i_a supplied form separate supply then i_a controls torque. (If we want more torque then we inject more i_a)
- Carbon brushes required sparking is common and brushes wear out – regular maintenance
- Quite expensive due to commutator and armature winding construction.
- Very common for small motors (tape recorders, CDs, drills, printers, photocopiers etc. In these cases, B is often supplied by a permanent magnet.
- Can put armature and field winding in series and run it directly off single phase household mains. This called a "universal motor". Used in lawn mowers, washing machines, cheap tools, hairdryers etc.



Three-Phase Induction Motors



Nikola Tesla





Introduction

Three-phase induction motors are the most common and frequently encountered machines in industry (*Workhorse of Industry*)

simple design, rugged, low-price, easy maintenance wide range of power ratings: fractional horsepower to 10 MW

run essentially as constant speed from no-load to full load

Its speed depends on the frequency of the power source

- not easy to have variable speed control
- requires a variable-frequency power-electronic drive for optimal speed control



Construction


An induction motor has two main parts

-a stationary stator

- consisting of a steel frame that supports a hollow, cylindrical core
- core, constructed from stacked laminations (why?), having a number of evenly spaced slots, providing the space for the stator winding
- Three-phase stator winding is either Star or Delta connected and coils are made of Copper conductors.



3-Phase Stator Winding





Rotor Construction

-a revolving rotor

composed of punched laminations, stacked to create a series of rotor slots, providing space for the rotor winding one of two types of rotor windings conventional 3-phase windings made of insulated wire (wound-rotor) » similar to the winding on the stator aluminum bus bars shorted together at the ends by two aluminum rings, forming a squirrel-cage shaped circuit (squirrel-cage)


Two basic design types depending on the rotor design

<u>squirrel-cage:</u> conducting bars laid into slots and shorted at both ends by shorting rings.

wound-rotor (Slip-Ring Rotor): complete set of three-phase windings exactly as the stator. Usually Y-connected, the ends of the three rotor wires are connected to 3 slip rings on the rotor shaft. In this way, the rotor circuit is accessible.




Rotor Showing Single Bars Short Circuited by 'End Rings'






Rotor Construction



Squirrel cage rotor


Wound rotor

Notice the slip rings






Slip Ring Rotor (Wound Rotor)



Cutaway in a typical wound-rotor IM.
Notice the brushes and the slip rings



Slip Ring Induction Motor



12/2/2023



Advantages of Slip Ring Induction Motor

- The main advantage of a slip ring induction motor is that its speed can be controlled easily.
- It has a high starting torque when compared to squirrel cage induction motor. Approximately 200 - 250% of its full-load torque.
- A squirrel cage induction motor takes 600% to 700% of the full load current, but a slip ring induction motor takes a very low starting current approximately 250% to 350% of the full load current



Advantages of Slip Ring Induction Motor

- Initial and maintenance cost is more compared to squirrel cage motor because presence of slip rings, brushes, short circuiting devices etc.
- Speed regulation is poor when operated with external resistances in rotor circuit.
- Efficiency and power factor of slip ring motor is lower compared to squirrel cage induction motor.
- Sensitivity to fluctuations in supply voltage

How Magnetic Field B is Produced

Electrical frequency is

$$\omega_e = 2\pi f_e$$
 elec. rads/s

B rotates in space at

$$\omega_S = \frac{2}{P} \omega_e^{\text{mech. rads/s}}$$

 $\omega_{\scriptscriptstyle S}$ is called the synchronous speed. Or $n_{\scriptscriptstyle S}{=}120 \mbox{\it f/P}$ in rpm.

The greater no. of poles, the slower the synchronous speed


f_e	$\omega_{\rm e} = 2\pi f_e$	P	ω_s (rad/s)	n _s (rpm)
50	314	2	314	3000
50	314	4	157	1500
50	314	6	105	1000
50	314	8	78	750
50	314	10	63	600



Balanced three phase windings, i.e. mechanically displaced 120 degrees form each other, fed by balanced three phase source A rotating magnetic field with constant magnitude is produced, rotating with a speed

$$n_{sync} = \frac{120f_e}{P} \quad rpm$$

Where f_e is the supply frequency and P is the no. of poles and n_{sync} is called the synchronous speed in rpm (revolutions per minute)






1 rpm = 2π radians/minute = $2\pi/60$ radian/second (rad-s⁻¹)


Therefore 1 rad-s⁻¹ = $60/2\pi \approx 10 \text{ rpm}$

Stator windings of an Induction Machine (IM) can only be wound in one way. P is fixed for an individual machine. An IM can either be a 2-pole machine, or a 4-pole machine oretc












$$\begin{split} B_{net}(t) &= B_a(t) + B_b(t) + B_c(t) \\ &= B_M \sin(\omega t) \angle 0^\circ + B_M \sin(\omega t - 120^\circ) \angle 120^\circ + B_M \sin(\omega t - 240) \angle 240^\circ \\ &= B_M \sin(\omega t) \hat{\mathbf{x}} \\ &- [0.5B_M \sin(\omega t - 120^\circ)] \hat{\mathbf{x}} - [\frac{\sqrt{3}}{2} B_M \sin(\omega t - 120^\circ)] \hat{\mathbf{y}} \end{split}$$


$$-[0.5B_{M} \sin(\omega t - 240^{\circ})]\hat{\mathbf{x}} + [\frac{\sqrt{3}}{2}B_{M} \sin(\omega t - 240^{\circ})]\hat{\mathbf{y}}$$







$$B_{net}(t) = [B_M \sin(\omega t) + \frac{1}{4}B_M \sin(\omega t) + \frac{\sqrt{3}}{4}B_M \cos(\omega t) + \frac{1}{4}B_M \sin(\omega t) - \frac{\sqrt{3}}{4}B_M \cos(\omega t)]\hat{\mathbf{x}}$$
$$+ [-\frac{\sqrt{3}}{4}B_M \sin(\omega t) - \frac{3}{4}B_M \cos(\omega t) + \frac{\sqrt{3}}{4}B_M \sin(\omega t) - \frac{3}{4}B_M \cos(\omega t)]\hat{\mathbf{y}}$$


$$= [1.5B_M \sin(\omega t)]\hat{\mathbf{x}} - [1.5B_M \cos(\omega t)]\hat{\mathbf{y}}$$






















Principle of operation

- This rotating magnetic field cuts the rotor windings and produces an induced voltage in the rotor windings
- Due to the fact that the rotor windings are short circuited, for both squirrel cage and wound-rotor, and induced current flows in the rotor windings
- The rotor current produces another magnetic field
- A torque is produced as a result of the interaction of those two magnetic fields

$$\tau_{ind} = kB_R \times B_s$$

• Where τ_{ind} is the induced torque and B_R and B_S are the magnetic flux densities of the rotor and the stator respectively



Induction motor speed

At what speed will the IM run?

Can the IM run at the synchronous speed, why?

- If rotor runs at the synchronous speed, which is the same speed of the rotating magnetic field, then the rotor will appear stationary to the rotating magnetic field and the rotating magnetic field will not cut the rotor. So, no induced current will flow in the rotor and no rotor magnetic flux will be produced so no torque is generated and the rotor speed will fall below the synchronous speed
- When the speed falls, the rotating magnetic field will cut the rotor windings and a torque is produced

12/2/2023 Electrical Machines 3



Induction motor speed

- So, the IM will always run at a speed lower than the synchronous speed
- The difference between the motor speed and the synchronous speed is called the Slip

$$n_{slip} = n_{sync} - n_m$$

Where n_{slip} = slip speed n_{sync} = speed of the magnetic field n_m = mechanical shaft speed of the motor

12/2/2023 Electrical Machines



The Slip

$$S = \frac{n_{\text{sync}} - n_{\text{m}}}{n_{\text{sync}}}$$

Where *s* is the *slip*

Notice that: if the rotor runs at synchronous speed

$$s = 0$$

if the rotor is stationary

$$s = 1$$

Slip may be expressed as a percentage by multiplying the above eq. by 100, notice that the slip is a ratio and doesn't have units



Induction Motors and Transformers

Both IM and transformer works on the principle of induced voltage

- Transformer: voltage applied to the primary windings produce an induced voltage in the secondary windings
- Induction motor: voltage applied to the stator windings produce an induced voltage in the rotor windings
- The difference is that, in the case of the induction motor, the secondary windings can move
- Due to the rotation of the rotor (the secondary winding of the IM), the induced voltage in it does not have the same frequency of the stator (the primary) voltage



Frequency

The frequency of the voltage induced in the rotor is given by

$$f_r = \frac{P \times n}{120}$$

Where f_r = the rotor frequency (Hz) P = number of stator poles n = slip speed (rpm)

$$f_r = \frac{P \times (n_s - n_m)}{120}$$
$$= \frac{P \times sn_s}{120} = sf_e$$



Frequency

What would be the frequency of the rotor's induced voltage at any speed n_m ?

 $|f_r = s f_e|$

When the rotor is blocked (s=1), the frequency of the induced voltage is equal to the supply frequency On the other hand, if the rotor runs at synchronous speed (s = 0), the frequency will be zero



Torque

- While the input to the induction motor is electrical power, its output is mechanical power and for that we should know some terms and quantities related to mechanical power
- Any mechanical load applied to the motor shaft will introduce a Torque on the motor shaft. This torque is related to the motor output power and the rotor speed

$$au_{load} \equiv rac{P_{out}}{\omega_m} \quad N_m$$
 and

$$\omega_{m} = \frac{2\pi n_{m}}{60} \quad rad/s$$



Horse power

- Another unit used to measure mechanical power is the Horse power (HP)
- It is used to refer to the mechanical output power of the motor
- Since we, as an electrical engineers, deal with watts as a unit to measure electrical power, there is a relation between horse power and watts

hp = 746 watts



Example

- A 208-V, 10 HP, four pole, 60 Hz, Y-connected induction motor has a full-load slip of 5 percent
 - 1. What is the synchronous speed of this motor?
 - 2. What is the rotor speed of this motor at rated load?
 - 3. What is the rotor frequency of this motor at rated load?
 - 4. What is the shaft torque of this motor at rated load?



Solution

1.
$$n_{sync} = \frac{120f_e}{P} = \frac{120(60)}{4} = 1800 \ rpm$$

2.

$$n_m = (1-s)n_s$$

$$= (1-0.05) \times 1800 = 1710 \ rpm$$

$$f_r = sf_e = 0.05 \times 60 = 3Hz$$

$$\tau_{load} = \frac{P_{out}}{\omega_m} = \frac{P_{out}}{2\pi \frac{n_m}{60}}$$

$$= \frac{10 \, hp \times 746 \, watt \, / \, hp}{1710 \times 2\pi \times (1/60)} = 41.7 \, N.m$$



Example

- **2.** A 3-phase cage rotor induction motor with 3 pole-pairs is fed from 50Hz supply and runs at 960 rpm generating a torque of 40 Nm. Determine:
- (i) The angular velocity (in rpm) of the rotating field produced by the stator winding,
 - (ii) The slip at which the machine is operating,
 - (iii) The frequency of the rotor currents flows,
 - (iv) The mechanical power produced by the machine.

(**Ans:** 1000 rpm, 4%, 2 Hz, 4.02 kW)

Given.

No. of pole pair = 3 [6 poles] frequency [f] = 50 HZ Motor speed (A. Ma) = 960 mpm Torque (Tm) = 40 Nm.

(i) Speed of Revolving mag. field of Tofind of stator (ns) = 12st = 180×20 = 1000 2 bw


Slip (S) = ns-hr x100 %. = 1000-960 ×100 = 0.04 (iii) frequency of notor current (fg) = Sf

(iv) Prech = 2Thata wates = 2×TT×960 X40 Mech = 4.02 KW



Example

3. If the e.m.f. in the stator of an 8-pole induction motor has a frequency of 50 Hz and that in the rotor of 1.5 Hz, at what speed is the motor running and what is the slip.



Example

4. A 6-pole, 3-pha, 50 Hz induction motor develops a full load torque of 150 Nm when the rotor current makes 120 complete cycles per minute. Determine the shaft power output.

Given:

$$f = 50 \text{ Hz}$$

$$T_m = 150 \text{ Hm}$$


$$f_n = 2 \text{ Hz} \left(120 \text{ cycles /ncin} \right)$$

$$Find \quad \text{Shaft}$$

$$\Rightarrow \text{Shaft} = \frac{2 \pi N_T T_m}{b_0} \times b_0$$

$$S = \frac{120 f}{p} = \frac{120 \times 50}{b} = \frac{1000 \text{ spm}}{b}$$

$$S = \frac{f_n}{f} = \frac{2}{50} = 0.04$$





Practice Problems

A 3-phase 50 Hz, 400 V induction motor has 6 poles and operates with a slip of 3% at a certain load. Determine;

- (i) the speed of the rotor.
- (ii) the frequency of rotor current.
- (iii) the speed of the rotor magnetic field with respect to stator.
- (iv) the speed of the rotor magnetic field with respect to the rotor.
- (v) the speed of the rotor magnetic field with respect to the stator magnetic field.